




Pos	Part Number	Description	Additional Text	Quantity
1	76011075100	WIRING HARNESS		1.00
2	000700000BH	SPARE CONNECTOR BH 6-PINS	DIAGNOSTIC PORT	1.00
3	75011088010	FUSE 10A 07		0.00
4	75011088015	FUSE 15A 07		0.00
5	75011087050	RUBBER CASING FOR FUSE BOX		1.00
7	0081650121	EJOT PT SCREW K50X12 WN5452		1.00
9	76011060000	HORN CPL.		1.00
10	49007439000	CLAMP RSGU 15/12		1.00
11	78105081010	SCREW TORX M5X10		1.00
12	69008021080	clip nut M5		1.00
15	76011057000	BRACKET F. FUSE BOX		1.00
16	78105081010	SCREW TORX M5X10		2.00
17	69008021080	clip nut M5		2.00
20	44011076200	Cable tie 200/4.6mm black		0.00
21	60011093045	RUBBER CABLE TIE 45MM 03		0.00
25	44611207200	FLASHER UNIT 97		1.00
26	58211031100	BRACKET FOR FLASHER RELAY		1.00
27	58411096100	DIODE S3H-15 97		1.00

29	76511010000	MAP-SELECT-SWITCH		1.00
30	76511010050	RUBBER HOLDER F. MAP-SEL-SWIT.		1.00
33	76011048000	AMBIENT-AIR TEMP. SENSOR CABLE		1.00