




| Pos | Part Number | Description                 | Additional Text | Quantity |
|-----|-------------|-----------------------------|-----------------|----------|
| 1   | 76011075100 | WIRING HARNESS              |                 | 1.00     |
| 2   | 000700000BH | SPARE CONNECTOR BH 6-PINS   | DIAGNOSTIC PORT | 1.00     |
| 3   | 75011088010 | FUSE 10A 07                 |                 | 0.00     |
| 4   | 75011088015 | FUSE 15A 07                 |                 | 0.00     |
| 5   | 75011087050 | RUBBER CASING FOR FUSE BOX  |                 | 1.00     |
| 7   | 0081650121  | EJOT PT SCREW K50X12 WN5452 |                 | 1.00     |
| 8*  | 0024060206  | HH collar screw M6x20 TX30  |                 | 1.00     |
| 9*  | 76011060100 | DC HORN 12V                 |                 | 1.00     |
| 10  | 49007439000 | CLAMP RSGU 15/12            |                 | 1.00     |
| 11  | 78105081010 | SCREW TORX M5X10            |                 | 3.00     |
| 12  | 69008021080 | clip nut M5                 |                 | 1.00     |
| 15  | 76011057000 | BRACKET F. FUSE BOX         |                 | 1.00     |
| 17  | 69008021080 | clip nut M5                 |                 | 2.00     |
| 20  | 44011076200 | Cable tie 200/4.6mm black   |                 | 0.00     |
| 21  | 60011093045 | RUBBER CABLE TIE 45MM 03    |                 | 0.00     |
| 25  | 44611207200 | FLASHER UNIT 97             |                 | 1.00     |
| 26  | 58211031100 | BRACKET FOR FLASHER RELAY   |                 | 1.00     |
| 27  | 58411096100 | DIODE S3H-15 97             |                 | 1.00     |

|    |             |                                |  |      |
|----|-------------|--------------------------------|--|------|
| 29 | 76511010000 | MAP-SELECT-SWITCH              |  | 1.00 |
| 30 | 76511010050 | RUBBER HOLDER F. MAP-SEL-SWIT. |  | 1.00 |
| 33 | 76011048000 | AMBIENT-AIR TEMP. SENSOR CABLE |  | 1.00 |

\* = New part