




Pos	Part Number	Description	Additional Text	Quantity
1	76011075100	WIRING HARNESS		1.00
2	000700000BH	SPARE CONNECTOR BH 6-PINS	DIAGNOSTIC PORT	1.00
3	75011088010	FUSE 10A 07		0.00
4	75011088015	FUSE 15A 07		0.00
5	75011087050	RUBBER CASING FOR FUSE BOX		1.00
7	0081650121	EJOT PT SCREW K50X12 WN5452		1.00
8	0024060206	HH collar screw M6x20 TX30		1.00
9	76011060100	DC HORN 12V		1.00
10	49007439000	CLAMP RSGU 15/12		1.00
11	78105081010	SCREW TORX M5X10		3.00
12	69008021080	clip nut M5		1.00
15	76011057000	BRACKET F. FUSE BOX		1.00
17	69008021080	clip nut M5		2.00
20	44011076200	Cable tie 200/4.6mm black		0.00
21	60011093045	RUBBER CABLE TIE 45MM 03		0.00
25	76511030000	FLASHER UNIT		1.00
26	58211031100	BRACKET FOR FLASHER RELAY		1.00
27	58411096100	DIODE S3H-15 97		1.00

29	76511010000	MAP-SELECT-SWITCH		1.00
30	76511010050	RUBBER HOLDER F. MAP-SEL-SWIT.		1.00
33	76011048000	AMBIENT-AIR TEMP. SENSOR CABLE		1.00