



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|-------------|--------------------------------|-----------------|----------|
| 1 | 76011075100 | WIRING HARNESS | | 1.00 |
| 2 | 000700000BH | SPARE CONNECTOR BH 6-PINS | DIAGNOSTIC PORT | 1.00 |
| 3 | 75011088010 | FUSE 10A 07 | | 0.00 |
| 4 | 75011088015 | FUSE 15A 07 | | 0.00 |
| 5 | 75011087050 | RUBBER CASING FOR FUSE BOX | | 1.00 |
| 7 | 0081650121 | EJOT PT SCREW K50X12 WN5452 | | 1.00 |
| 8 | 0024060206 | HH collar screw M6x20 TX30 | | 1.00 |
| 9 | 76011060100 | DC HORN 12V | | 1.00 |
| 10 | 49007439000 | CLAMP RSGU 15/12 | | 1.00 |
| 11 | 78105081010 | SCREW TORX M5X10 | | 3.00 |
| 12 | 69008021080 | clip nut M5 | | 1.00 |
| 15 | 76011057000 | BRACKET F. FUSE BOX | | 1.00 |
| 17 | 69008021080 | clip nut M5 | | 2.00 |
| 20 | 44011076200 | CABLE TIE 200/3,6MM BLACK | | 0.00 |
| 21 | 60011093045 | RUBBER CABLE TIE 45MM 03 | | 0.00 |
| 24 | 76011025000 | ADAPTER CABLE FLASHER UNIT LED | | 1.00 |
| 25 | 76011030000 | FLASHER UNIT LED 6,25W | | 1.00 |
| 26 | 58211031100 | BRACKET FOR FLASHER RELAY | | 1.00 |

| | | | | |
|----|-------------|--------------------------------|--|------|
| 27 | 58411096100 | DIODE S3H-15 97 | | 1.00 |
| 29 | 76511010000 | MAP-SELECT-SWITCH | | 1.00 |
| 30 | 76511010050 | RUBBER HOLDER F. MAP-SEL-SWIT. | | 1.00 |
| 33 | 76011048000 | AMBIENT-AIR TEMP. SENSOR CABLE | | 1.00 |