



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|----------------|--------------------------------|-----------------|----------|
| 1 | 0618081210 | NEEDLE BUSH HK 0810 DIN 618 | | 1.00 |
| 2 | M3235053000V01 | WATER PUMP SHAFT T26 | | 1.00 |
| 3 | 0770060015 | O-ring 6,00x1,50 NBR 70 | | 1.00 |
| 4 | M3235053001 | CIRCLIP J28 DIN472 | | 1.00 |
| 5 | 0625060016 | deep groove ball bearing 6001. | | 1.00 |
| 7 | M3235052000V10 | WEAR BUSH | | 1.00 |
| 8 | 0770048015 | O-RING 48,00X1,50 | | 1.00 |
| 9 | 0770016020 | O-RING 16X2 NBR | | 1.00 |
| 10 | M3235051000 | WATER PUMP CASE | | 1.00 |
| 11 | 0760123073 | SHAFT SEAL RING 12X30X7 PTFE | DOUBLE-LIP | 1.00 |
| 12 | B3335055000 | WATER PUMP WHEEL | | 1.00 |
| 13 | 61230045000 | CAP NUT M6 STAINLESS STEEL | | 1.00 |
| 14 | M3235004000 | GASKET WATER PUMP | | 1.00 |
| 15 | B3335058000 | WAPU COVER | | 1.00 |
| 16 | 58030010200 | SCREW IN NOZZLE M20X1,5 | | 1.00 |
| 17 | 0025060256 | HH collar screw M6x25 TX30 | | 2.00 |
| 18 | 0025060506 | HH collar screw M6x50 TX30 | | 2.00 |

| | | | | |
|----|----------------|------------------------------|-------------------------|------|
| 19 | 59030022100 | BLEEDER FLANGE M12X1,5 WS=13 | | 1.00 |
| 20 | 58335099000 | HOSE CLAMP GEMI 10-16 | | 2.00 |
| 21 | M3234038053 | RADIATOR HOSE | | 1.00 |
| 22 | 0770010015 | O-RING 10,00X1,50 NBR 70 SH | | 1.00 |
| 23 | M3235019000V01 | WATER CONNECTOR | | 1.00 |
| 24 | 0603061001 | CU-SEAL RING DIN7603-6X10X1 | | 1.00 |
| 25 | 0015060083 | HH COLLAR SCREW M 6X8 WS=8 | LC4, LC4 SM, DUKE | 1.00 |
| 26 | 0025060126 | HH collar screw M6x12 TX30 | | 3.00 |
| 27 | B3334038060 | HEAT EXCHANGER | | 1.00 |
| 28 | 0770110021 | O-RING 11X2 VITON | FOR EXC+MXC GAS COCK | 3.00 |
| 30 | 0025050166 | HH collar screw M5x16 TX30 | | 1.00 |
| 31 | 0770015020 | O-RING 15,00X2,00 | | 1.00 |