




Pos	Part Number	Description	Additional Text	Quantity
0	58311121100	FLASHER SUPPORT R/S DUKE'94		1.00
1	58311065100	* TACHOMETER 10000 RPM '96		1.00
2*	58311065150	CABLE FOR TACHOMETER '97		1.00
3	58311029100	INSTRUMENT LIGHTS 12V		2.00
4	58311053000	HEXAGON NUT M5X15 WS=8		4.00
5	58311088100	REDUCTION RUBBER		4.00
6	58311188000	*SPEEDOMETER CABLEM12/12 845MM		1.00
7	49111425000	BULB 12V 1,2W (W2X4,6D)		4.00
8	58311068100	* SPEEDOMETER KMH DUKE'94		1.00
8*	58311068300	SPEEDOMETER MILES DUKE'96		1.00
9	58311052060	TRIPMETER RESET KNOB		1.00
10	0984020051	OVAL H.SCREW DIN7984-M 2X 5		1.00
11	58301098100	PLASTIC CAP 3/8" 261		1.00
12	58311054000	FOAM RUBBER RING 81x97x10		2.00
13	58312112000	* RUBBER RING 16 X 22 X 7		1.00
15	58311051000	INSTRUMENTS BRACKET		1.00

16	58311051050	BRACKET FOR INSTRUMENT BRACKET		1.00
17	54335031200	RUBBER GROMMET 20X25-M6X10 (2)		1.00
18	44012057000	SILENTBL.20X20-M6X15(2)45SHORE		2.00
19	0125060003	WASHER DIN0125-A 6,4		0.00
20	0797060003	TOOTH LOCK WASH. DIN6797-A 6,4		0.00
21	0934060003	Hex. nut DIN 934 M6		6.00
22	58311021100	FLASHER SUPPORT L/S DUKE'94		1.00
23	0912060123	AH SCREW DIN0912-M 6X12		2.00
30	58311066044	* LOCK SET CPL. DUKE'94		1.00
33	0985040123	FLAT HEAD SCREW DIN7985-M 4X12		2.00
40	58011021200	HIGH BEAM INDICATOR LIGHT BLUE		1.00
41	58011023200	NEUTRAL INDICATOR LIGHT GREEN		1.00
42	58011022200	TEMPERATURE WARNING LIGHT RED		1.00
43	58011024200	FLASHER INDICATOR LIGHT GREEN		1.00
44	58011022300	OIL WARNING LIGHT RED		1.00
45	58411078000	INDICATOR LIGHT WIRING '96		1.00

* = New part