






625 SC

625 SC SUPERMOTO



ACHTUNG !!!
EINBAU OHNE PLASTIKMUTTERN!
CAUTION !!!
WITHOUT PLASTIC NUT FITTING!

Pos	Part Number	Description	Additional Text	Quantity
1*	58314060000	SPEEDOMET.BRACKET M.A.E. 2002		1.00
2*	58314033100	FLASHER BRACKET 2002	EXC EU+AUS	1.00
3*	0021050003	washer DIN 9021 A - 5.3		2.00
4*	0985050003	Self locking nut DIN 985 M5		2.00
5*	58214069051	rubber grommet 16x10.8x3		2.00
6*	58314069100	SPEEDOMETER KM/H F. 21" 0	625 SC	1.00
6*	58314069400	SPEEDOMETER KM/H F. 17" 0	625 SC SUPERMOTO	1.00
6*	58314069300	SPEEDOMETER MPH F. 21" 0	625 SC	0.00
6*	58314069500	SPEEDOMETER MPH F. 17" 02	625 SC SUPERMOTO	0.00
7	58314069151	CABLE FOR SIGMA 500 '98		1.00
8	55011022100	CLAMP D=6/8MM, BLACK		3.00
10*	58314069152	BRACKET F. TRIGGER SC-SM 02	625 SC SUPERMOTO	1.00
11	50314069050	MAGNET FOR DIGITALSPEEDOM.2000	625 SC	1.00
12	0471009104	CIRCLIP DIN0471- 9X1 INOX	625 SC	1.00

13*	58214069050	SENSOR MAGNET ADVENTURE 01	625 SC SUPERMOTO	1.00
14*	0799070000	TAB WASHER DIN6799-RS 7,0	625 SC SUPERMOTO	1.00
15	58011021300	H.BEAM INDICATOR LIGHT BLUE'98	EXC EU+AUS	1.00
16	58011024300	FLASHER INDICAT.LIGHT GREEN'98	EXC EU+AUS	1.00
17*	0014060253	HH COLLAR SCREW M 6X25 WS=8		2.00
18*	58314069155	ADAPT.CABLE SPEEDOM. M.A.E. 02		1.00
19*	31008060000	rubber grommet D=8mm open		2.00
20*	0934080003	Hexagon nut DIN934 M8		1.00
21*	58314060050	spacer bushing for speedometer		2.00
25*	58314069350	* BRACKET TRIPMASTER SWITCH 02	ADAPTER LIGHT SWITCH - EU	0.00
26*	58314068000	BATTERY F. SPEEDOM. M.A.E. 02	TYPE CR 2430	0.00
27*	58314069200	TRIPMASTER-SWITCH DIGI-SPEEDO.		0.00
28*	0963040203	FLAT HEAD SCREW DIN0963-M 4X20		0.00

* = New part