




| Pos | Part Number | Description                    | Additional Text | Quantity |
|-----|-------------|--------------------------------|-----------------|----------|
| 1   | 35480455S3  | AXLE CLAMP R/S CPL. W. TUBE    |                 | 1.00     |
| 2   | 35480456S2  | AXLE CLAMP L/S CPL. W. TUBE    |                 | 1.00     |
| 3   | 35480585    | Fork outer tube 36x425 dt42 db |                 | 2.00     |
| 4   | 95010055S   | SPRING 1,8 N/MM SET            |                 | 0.00     |
| 4   | 95010051S   | SPRING 2.0N/MM SET D=3.1MM     |                 | 1.00     |
| 4   | 95010052S   | SPRING 2,2 N/MM SET            |                 | 0.00     |
| 5   | 35480497    | Washer 22x30x2,5               |                 | 0.00     |
| 6   | 35480599S   | Screw cap M38x1,5 air d42 cpl. |                 | 1.00     |
| 7   | 35480600S   | Screw cap M38x1,5 d42 cpl.     |                 | 1.00     |
| 8   | 46180581    | O-ring 35x1,5 NBR70 yellow     |                 | 2.00     |
| 9   | 48601494S   | Schrader valve M8x1 cmpl.      |                 | 1.00     |

|    |             |                              |  |      |
|----|-------------|------------------------------|--|------|
| 11 | RP10021     | Adjuster kit screw cap       |  | 1.00 |
| 12 | 35480551S6  | pistonrod cpl. Right         |  | 1.00 |
| 13 | 35480551S7  | pistonrod cpl. Left          |  | 1.00 |
| 14 | 52000313    | Sticker warning 60x40        |  | 1.00 |
| 15 | 52000223SET | Sticker set XACT AER 140x141 |  | 1.00 |
| 16 | 35480583    | Stroke indicator d35 red     |  | 2.00 |
| 17 | 35480623    | Fork protection ring 48,4mm  |  | 2.00 |
| 18 | 0025060256  | HH collar screw M6x25 TX30   |  | 2.00 |
| 94 | 48601166S1  | Fork Fluid Viscosity 4.0 5L  |  | 0.00 |
| 95 | T14034      | Fuchs grease IPR (250g)      |  | 0.00 |
| 96 | 00062010053 | special grease AER Fork 400g |  | 0.00 |
| 97 | RP10006     | BUSHING KIT 35MM             |  | 0.00 |
| 98 | RP10027     | gasket kit 35mm black        |  | 0.00 |
| 99 | RP10008     | REPAIR KIT 50+65SX AIR 2017  |  | 0.00 |