



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|-------------|--------------------------------|-----------------|----------|
| 1 | 76111075000 | Main wiring harness | | 1.00 |
| 2 | 76911076000 | Rear part, wiring harness | | 1.00 |
| 3 | 75011088010 | FUSE 10A 07 | | 0.00 |
| 4 | 75011088015 | FUSE 15A 07 | | 0.00 |
| 5 | 75011087050 | RUBBER CASING FOR FUSE BOX | | 1.00 |
| 6 | 60311034000 | VOLTAGE REGULATOR | | 1.00 |
| 7 | 54603048100 | clip nut M6 | | 2.00 |
| 8 | 76111075010 | Wiring harness, voltage regula | | 1.00 |
| 9 | 0025060206S | HH collar screw M6x20 TX30 | | 2.00 |
| 10 | 0985060003 | Self lock. nut DIN985-M6-A2 | | 1.00 |
| 11 | 44011076140 | CABLE TIE 140/2,5MM BLACK | | 0.00 |

| | | | | |
|----|----------------|--------------------------------|-----------------|------|
| 11 | 44011076200 | CABLE TIE 200/3,6MM BLACK | | 0.00 |
| 11 | 44011076305 | CABLE TIE 300/4,8MM BLACK | | 0.00 |
| 12 | 60011093045 | RUBBER CABLE TIE 45MM 03 | | 0.00 |
| 13 | 58411096100 | DIODE S3H-15 97 | | 3.00 |
| 14 | 64111060033 | Direct current horn complete | | 1.00 |
| 15 | 000700000BH | SPARE CONNECTOR BH 6-PINS | DIAGNOSTIC PORT | 1.00 |
| 16 | 61434051000 | Shift shaft sensor | | 1.00 |
| 17 | 76834052000 | Quickshifter sensor cover | | 1.00 |
| 18 | 000700000OE001 | dummy connector OE 33-Pins | | 1.00 |
| 19 | 61011055045 | EDGE PROTECTOR L=45MM 05 | | 1.00 |
| 34 | 014580050203S | Cap hd. screw DIN14580 M5x20 P | | 2.00 |
| 35 | 78003123070 | Spacing tube spring retaining | | 2.00 |