



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|--------------|------------------------------|-----------------|----------|
| 1 | C90111075000 | Main wiring harness | | 1.00 |
| 2 | 61111057000 | RELAY CM1A-R-12V-H80 07 | | 5.00 |
| 3 | 75011087050 | RUBBER CASING FOR FUSE BOX | | 1.00 |
| 4 | 75011088010 | FUSE 10A 07 | | 0.00 |
| 5 | 61111018100 | Temperatur sensor | | 1.00 |
| 6 | 64111197000 | mass cable tank-frame | | 1.00 |
| 7 | C90011096000 | mass cable starter-frame | | 1.00 |
| 8 | 64111097000 | mass cable starter-battery | | 1.00 |
| 9 | 64111059000 | starter cable | | 1.00 |
| 10 | C90111076033 | Rear Harness cpl. | | 1.00 |
| 11 | 64111059050 | battery cable | | 1.00 |
| 12 | 64111058010 | Cover cap starter relay | | 1.00 |
| 13 | 0912060083 | AH collar screw DIN 912 M6x8 | | 2.00 |

| | | | | |
|----|--------------|----------------------------|--|------|
| 14 | 58011109130 | Plug-in fuse, big 30A | | 2.00 |
| 15 | 76211058000 | Starter relay | | 1.00 |
| 18 | 64111060133 | Direct current horn cpl. | | 1.00 |
| 19 | 0024060106 | HH COLLAR SCREW M6X10 TX30 | | 1.00 |
| 20 | C90711034000 | Voltage regulator | | 1.00 |
| 21 | 0025060206S | HH collar screw M6x20 TX30 | | 2.00 |
| 22 | 60011093045 | RUBBER CABLE TIE 45MM 03 | | 0.00 |
| 23 | 44011076140 | CABLE TIE 140/2,5MM BLACK | | 0.00 |
| 23 | 44011076200 | CABLE TIE 200/3,6MM BLACK | | 0.00 |
| 24 | 69011092000 | Cable tie w. socket D=6.5 | | 1.00 |
| 25 | 0025060126 | HH collar screw M6x12 TX30 | | 1.00 |
| 26 | 58411098100 | CONTACT WASHER M6 VSV-K6 | | 2.00 |
| 27 | 0025060166 | HH collar screw M6x16 TX30 | | 1.00 |