




| Pos | Part Number | Description                   | Additional Text | Quantity |
|-----|-------------|-------------------------------|-----------------|----------|
| 1   | 0625062062  | BALL BEARING 6206 C3 J1 NSK   |                 | 1.00     |
| 2   | 0405263113  | NEEDLE BEAR. K 26-31-13       |                 | 1.00     |
| 3   | 60033005000 | IDLER GEAR 5.G "600 5P24"     |                 | 1.00     |
| 4   | 60033042000 | STOP DISK 28,3/35,75/1,5      |                 | 1.00     |
| 5   | 0417280150  | LOCK RING DIN5417-WS28        |                 | 1.00     |
| 6   | 60033003000 | SLIDING G 3/4.G "600 34P18/20 |                 | 1.00     |
| 7   | 60033041000 | STOP DISK 22,2/30,2/1,5       |                 | 1.00     |
| 8   | 0405222613  | NEEDLE BEAR. K 22X26X13 TN    |                 | 1.00     |
| 9   | 60033006000 | IDLER GEAR 6.G "600 6P27"     |                 | 1.00     |
| 10  | 60033002100 | SOLID GEAR 2.G. "600 2P15-1"  |                 | 1.00     |
| 11  | 60033040015 | STOP DISK 20,2X28X1,5         |                 | 0.00     |
| 11  | 60033040016 | STOP DISK 20,2/28/1,6         |                 | 0.00     |
| 11  | 60033040017 | STOP DISK 20,2/28/1,7         |                 | 0.00     |
| 11  | 60033040018 | STOP DISK 20,2/28/1,8         |                 | 0.00     |
| 11  | 60033040019 | STOP DISK 20,2/28/1,9         |                 | 0.00     |
| 11  | 60033040020 | STOP DISK 20,2/28/2,0         |                 | 0.00     |
| 11  | 60033040021 | STOP DISK 20,2/28/2,1         |                 | 0.00     |
| 11  | 60033040022 | STOP DISK 20,2/28/2,2         |                 | 0.00     |
| 12  | 60033001000 | MAIN SHAFT 12-T 03            |                 | 1.00     |
| 13  | 0618091312  | NEEDLE BUSH HK0912 9/13/12 03 |                 | 1.00     |
| 14  | 0625062040  | BALL BEARING 6204 DU J1 C3    |                 | 1.00     |