




Pos	Part Number	Description	Additional Text	Quantity
1	63530065000	Gearbox lubrication pipe cmpl.		1.00
2	0770010010	o-ring 10.00x1.00 NBR70		1.00
4	63538051000	gasket with support sheet		1.00
5	A61838850010	Connecting plate cmpl.		1.00
6	A61838076033	radioator bracket cpl.		1.00
7	63538035000	oil line		1.00
8	63530086010	pressure plate		1.00
9	0019050121S	INT. TORX FLAT HEAD M5X12 T25		1.00

10	014580060166S	SHCS ISO 14580 M6x16 SL		6.00
11	63638003000	Bearing bolt		1.00
12	63538001022	oil pump idler wheel 22 teeth	L-PART	1.00
13	0799080000	retaining washer DIN 6799 - 8		1.00
14	60038007010	washer 10x16x0.5		1.00
15	60038001224	oil pump gear 24 teeth		1.00
16	63538008050	oil pump cover plate		2.00
17	60038011100	eaton pump set 14mm	L-PART	1.00
18	63538002000	oil pump shaft		1.00
19	0402041580	needle roller NRB 4x15.8 G2		3.00
20	0402050980	needle roller DIN 5402 5x9.8		2.00
21	0770120020	O-RING 12,00X2,00 NBR 70		2.00
22	63538012000	Oil Pumphousing		1.00
23	0770140200	O-RING 14,00X2,00		4.00
24	0770020020	O-RING 20X2 VITON		1.00
25	60038128000	control piston		1.00
26	A61838026000	Oil pressure regulator		1.00
27	50337073000	shim		1.00
28	61238010100	eaton pump set 30mm	L-PART	1.00
30	0025060256	HH collar screw M6x25 TX30		5.00
31	63530086000	oil sump gasket		1.00
33	6353008500024	oil pan		1.00
34	61238021100	oil screen cpl.		2.00
37	0770125015	O-RING 12,5X1,5 NBR		2.00
38	0770170200	O-RING 17,00X2,00		2.00
40	61338015200	OIL FILTER		1.00
41	07700390261	O-RING 39,34X2,62		1.00
42	75038041200	oil filter cover		1.00
43	A65338005015	Hex screw M5x15 ISA perforated		2.00
44	59030023000	dowel sleeve 6x8x11.5		3.00
45	0025060356	HH collar screw M6x35 TX30		5.00
46	0025060306	HH collar screw M6x30 TX30		10.00
47	0770060025	O-RING 6X2.5		2.00
48	0025080166S	HH collar screw M8x16 TX40 SL		1.00
49	0770070025	O-Ring 7x2,50 HNBR		1.00
50	0025060206S	HH collar screw M6x20 TX30		2.00
51	A61838034000	oil line left		1.00
52	A61838035000	oil line right		1.00
53	A61838855000	Oil cooler		1.00
99	61938021344	Oilfilter service kit		0.00