



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|-------------|----------------------------|-------------------------|----------|
| 1 | 75611075200 | MAIN WIRING HARNESS | | 1.00 |
| 2 | 000700000BH | SPARE CONNECTOR BH 6-PINS | DIAGNOSTIC PORT | 1.00 |
| 3 | 75011088010 | FUSE 10A 07 | | 0.00 |
| 4 | 75011088015 | FUSE 15A 07 | | 0.00 |
| 5 | 75011087050 | RUBBER CASING FOR FUSE BOX | | 1.00 |
| 7 | 0081050121 | EJOT PT screw K50x12 | only for US and SixDays | 5.00 |
| 8 | 0024060106 | HH COLLAR SCREW M6X10 TX30 | | 1.00 |
| 9 | 62511060000 | DC HORN 05 | | 1.00 |
| 10 | 49007439000 | CLAMP RSGU 15/12 | | 1.00 |
| 11 | 75611083000 | BRACKETS FOR PLUGS 08 | | 1.00 |
| 20 | 44011076140 | CABLE TIE 140/2,5MM BLACK | | 0.00 |
| 20 | 44011076200 | CABLE TIE 200/3,6MM BLACK | | 0.00 |
| 20 | 44011076305 | CABLE TIE 300/4,8MM BLACK | | 0.00 |
| 21 | 60011093075 | RUBBER CABLE TIE 75MM 03 | | 0.00 |
| 21 | 60011093045 | RUBBER CABLE TIE 45MM 03 | | 0.00 |
| 25 | 44611207200 | FLASHER UNIT 97 | | 1.00 |

| | | | | |
|----|-------------|--------------------------------|--|------|
| 26 | 58211031100 | BRACKET FOR FLASHER RELAY | | 1.00 |
| 27 | 58411096100 | DIODE S3H-15 97 | | 1.00 |
| 28 | 75611046000 | BRACKET MAP-SELECT-SWITCH | | 1.00 |
| 29 | 76511010000 | MAP-SELECT-SWITCH | | 1.00 |
| 30 | 76511010050 | RUBBER HOLDER F. MAP-SEL-SWIT. | | 1.00 |
| 33 | 75011047000 | AMBIENT-AIR TEMP. SENSOR CABLE | | 1.00 |