




Pos	Part Number	Description	Additional Text	Quantity
1	S454600024S0000	shock housing cpl		1.00
2	36120151ST	PLUG SCREW M5X6 CPL.		1.00
3	S208600003000FB	O-ring 5,28x1,78 HNBR70 red		1.00
4	50180095	HS cylinder-head screw R1/8 I8		1.00
5	RP10051T	Ball bearing kit		0.00
6	46181193	Pivotseal d.12X25,1 PDS		4.00
7	52000233	Sticker XPLOR PDS 90x40		1.00
8	S012900010S0400	Compression cpl.		1.00
9	RP10044T	Repair kit adjuster DCC 2023		0.00
10	50180217	O-ring 27x1,5 Viton70 green IS		1.00
11	50180218	O-ring 25x1,5 Viton70		1.00

12	S938100027S0000	Adjustment nut pds-shock plast		1.00
13	S80980001600020	Mainspring (59) 70-190.0 shock		0.00
13	S80980001700020	Mainspring (59) 75-190.0 shock		0.00
13	S80980001800020	Mainspring (59) 80-190.0 shock		1.00
13	S80980001900020	Mainspring (59) 85-190.0 shock		0.00
13	S80980002000020	Mainspring		0.00
14	RP10052T	Spring plate repair kit		0.00
15	46181656	nut M10x1 h10,5 SW19		1.00
16	46181416	Piston 15,4x35,4x6		1.00
17	S71100000500000	Compression holder 10x48		1.00
18	46811258	Washer 12x24x2,5		1.00
19	S624600000S0000	Piston d46 cmpl.		1.00
20	S25120000300000	Rebound disc 12x36x18,9 h14,9		1.00
21	S614620000S0100	Seal support 46x28 cmpl.		1.00
22	S23902000000000	round-wire snap ring 49x1,75		1.00
23	46181505	Cover 46,15x6,7 h14,7		1.00
24	S921800000000C1	Rubber pad 18x56x46 black		1.00
25	S421800021S0000	bottom part cpl. with piston r		1.00
98	50180751S1	SHOCK ABSORBER FLUID 5 LT		0.00
99	RP10053T	Repair kit shock absorber		0.00