



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|-------------|-----------------------------|-----------------|----------|
| 1 | 61111175000 | MAIN WIRING HARNESS SD-R 08 | | 1.00 |
| 2 | 61011083000 | BRACKET FOR PLUGS CPL. 05 | | 1.00 |
| 3 | 49007439000 | CLAMP RSGU 15/12 | | 1.00 |
| 4 | 0912050103 | AH SCREW DIN0912-M 5X10 | | 1.00 |
| 5 | 61011083020 | BRACKET FOR PLUGS COVER 05 | | 1.00 |
| 6 | 60003088000 | PLASTIC CAP FOR M6 03 | | 4.00 |
| 7 | 44611207200 | FLASHER UNIT 97 | | 1.00 |
| 8 | 61011075020 | DUMMY PLUG ALARM SYSTEM 05 | | 1.00 |
| 9 | 61111057050 | BRACKET RELAY 07 | | 1.00 |
| 10 | 0016050121 | SCREW FOR PLASTIC 50X12 | BLACK | 2.00 |
| 11 | 58411096100 | DIODE S3H-15 97 | | 2.00 |
| 12 | 61111057000 | RELAY CM1A-R-12V-H80 07 | | 4.00 |
| 13 | 75011088010 | FUSE 10A 07 | | 0.00 |

| | | | | |
|----|-------------|--------------------------------|-----------------|------|
| 14 | 75011088015 | FUSE 15A 07 | | 0.00 |
| 16 | 000700000BH | SPARE CONNECTOR BH 6-PINS | DIAGNOSTIC PORT | 1.00 |
| 17 | 58411098100 | CONTACT WASHER M6 VSV-K6 | | 1.00 |
| 18 | 0025060126 | HH collar screw M6x12 TX30 | | 1.00 |
| 19 | 61111079000 | WIRING HARNESS FRONT 07 | | 1.00 |
| 20 | 61011060000 | DC HORN CPL. 05 | | 1.00 |
| 21 | 0025060106 | HH collar screw M6x10 TX30 | | 2.00 |
| 22 | 60011092000 | OIL-PRESSURE SWITCH CABLE 03 | | 1.00 |
| 24 | 44011076100 | CABLE TIE 100/2,5MM BLACK | | 0.00 |
| 24 | 44011076200 | CABLE TIE 200/3,6MM BLACK | | 0.00 |
| 24 | 44011076305 | CABLE TIE 300/4,8MM BLACK | | 0.00 |
| 25 | 61011093000 | WIRING HOLDER 05 | | 1.00 |
| 26 | 58513001000 | SPIRAL HOSE D=9MM PER METER | 1 METER | 0.00 |
| 27 | 75011087050 | RUBBER CASING FOR FUSE BOX | | 1.00 |
| 28 | 61111020000 | STARTER INTERLOCK | | 1.00 |
| 29 | 61111018000 | TEMPERATURE SENSOR 07 | | 1.00 |
| 30 | 58111076000 | CABLE SUPPORT KHS NR.150-47610 | | 0.00 |
| 31 | 61111041000 | CABLE SUPPORT 07 | | 0.00 |