



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|---------------|--------------------------------|---------------------------|----------|
| 1 | 7501308010130 | BRAKE CALIPER BL. WITHOUT PADS | | 1.00 |
| 3 | 54613311200 | RETAINING SPRING SET | | 1.00 |
| 4 | 54613218000 | CUP SET SHORT | | 1.00 |
| 5 | 61013020200 | BLEEDER SCREW WITH CAP | | 1.00 |
| 7 | 50313083000 | BRAKE PISTON 32MM | | 1.00 |
| 8 | 50313081000 | REPAIR KIT SEALING RINGS 32MM | | 1.00 |
| 11 | 50313090000 | BRAKE PAD REAR TOSHIBA TTH38GF | | 1.00 |
| 12 | 61013082000 | BOLT SET 05 | | 1.00 |
| 13 | 50213025000 | HOLLOW SCREW M10X1X19 | FC, FE+FS (USA) | 1.00 |
| 14 | 0603100141 | sealing ring DIN 7603 10x14x1 | ONLY FOR LC4 ADVENTURE | 2.00 |
| 15 | 61013072000 | BRAKE PIPE REAR 05 | | 1.00 |