








ACHTUNG !!!
EINBAU OHNE PLASTIKMUTTERN!
CAUTION !!!
WITHOUT PLASTIC NUT FITTING!

Pos	Part Number	Description	Additional Text	Quantity
1	58314069100	SPEEDOMETER KM/H F. 21" 0	625 SC	1.00
1	58314069300	SPEEDOMETER MPH F. 21" 0	625 SC	1.00
2	58314068000	BATTERY F. SPEEDOM. M.A.E. 02	TYPE CR 2430	0.00
3	58214069051	rubber grommet 16x10.8x3		2.00
4	0021050003	washer DIN 9021 A - 5.3		2.00
5	0985050003	Self locking nut DIN 985 M5		2.00
6*	58411066400	LOCK SYSTEM 625 SXC 03	EU/AUS/GB	1.00
7*	50311066050	IGNITION LOCK NUT M24X1		1.00
8*	58411066450	WASHER F. IGNITION LOCK 03		1.00
9*	12003007052	SPRING L=16MM		1.00
10*	0137030003	SPRING WASHER DIN137 B3		1.00

11*	45002040091	GROOVED NAIL RIVETO AF10		1.00
12*	40011166200	KEY BLANK BLACK "T" GR		0.00
20	58314069200	TRIPMASTER-SWITCH DIGI-SPEEDO.		1.00
21	0965040251	FLAT HEAD SCREW M4X25		1.00
22*	58314060200	SPEEDOMET.BRACKET 625 SXC 03		1.00
23*	58312085100	EDGE PROTECTOR PER METER	0,097 METER	1.00
24*	31008060000	rubber grommet D=8mm open		2.00
25*	58011039000	SPACER BUSHING 6,5 X 8 X 7		2.00
26*	0014060253	HH COLLAR SCREW M 6X25 WS=8		2.00
27	58314033100	FLASHER BRACKET 2002	EXC EU+AUS	1.00
28	58011024300	FLASHER INDICAT.LIGHT GREEN'98	EXC EU+AUS	1.00
29	58011021300	H.BEAM INDICATOR LIGHT BLUE'98	EXC EU+AUS	1.00
30*	58314085000	INDICATOR LIGHT ORANGE "ON"		1.00
31*	50314068000	TRIPMASTER-SWITCH W. CLAMP 03	EXC USA	1.00
32*	50314068050	CLAMP FOR TRIPMASTER-SWITCH 03		1.00
33*	0965040125	FLAT HEAD SCREW DIN0966-M 4X20		1.00
34*	0934040003	HEXAGON NUT DIN0934-M 4		1.00
35*	0017060203	EJOT PT SCREW K60X20 WS=6	MXC, EXC	1.00
36*	58314060300	SPEEDOM.BRACKET 625 SXC USA 03		1.00
40*	58314069251	SPEEDOM. CABLE (WITHOUT NUTS)		1.00
41	55011022100	CLAMP D=6/8MM, BLACK		2.00
42*	54814069050	MAGNET FOR DIGITAL SPEEDOM. 03		1.00
43	0471009104	CIRCLIP DIN0471- 9X1 INOX	625 SC	1.00

* = New part