



Pos	Part Number	Description	Additional Text	Quantity
1	58314069400	SPEEDOMETER KM/H F. 17" 0	625 SC SUPERMOTO	1.00
1	58314069500	SPEEDOMETER MPH F. 17" 02	625 SC SUPERMOTO	1.00
2	58314068000	BATTERY F. SPEEDOM. M.A.E. 02	TYPE CR 2430	1.00
3	58214069051	rubber grommet 16x10.8x3		2.00
4	0021050003	washer DIN 9021 A - 5.3		2.00
5	0985050003	Self locking nut DIN 985 M5		2.00
20	58314069200	TRIPMASTER-SWITCH DIGI-SPEEDO.		1.00
21	0965040251	FLAT HEAD SCREW M4X25		1.00
22	58314060400	SPEEDOMET.BRACKET 660SM 03		1.00
24	31008060000	rubber grommet D=8mm open		2.00
25	58011039000	SPACER BUSHING 6,5 X 8 X 7		2.00
26	0014060253	HH COLLAR SCREW M 6X25 WS=8		2.00
27	58314033100	FLASHER BRACKET 2002	EXC EU+AUS	1.00
28	58011024300	FLASHER INDICAT.LIGHT GREEN'98	EXC EU+AUS	1.00
29	58011021300	H.BEAM INDICATOR LIGHT BLUE'98	EXC EU+AUS	1.00
40	58314069251	SPEEDOM. CABLE (WITHOUT NUTS)		1.00

41	55011022100	CLAMP D=6/8MM, BLACK		2.00
42	58214069050	SENSOR MAGNET ADVENTURE 01	625 SC SUPERMOTO	1.00
43	0471009104	CIRCLIP DIN0471- 9X1 INOX	625 SC	1.00
44	58314052000	BRACKET F. SENSOR SM 03		1.00
45	0084040063	CYL.HEAD SCREW DIN0084-M 4X 6A		2.00