



| Pos | Part Number | Description                    | Additional Text                | Quantity |
|-----|-------------|--------------------------------|--------------------------------|----------|
| 1   | 90633001000 | MAIN SHAFT CPL.                |                                | 1.00     |
| 3   | 90133001011 | COLLAR BUSHING MAIN SHAFT      | for clutch hub w/o brass inlay | 1.00     |
| 4   | J005060123  | FLAT HEAD SCREW M6X12 PH       |                                | 1.00     |
| 5   | 90130004002 | LOCK WASHER F.BEARING DRIVE    |                                | 1.00     |
| 6   | J625062040  | GROOVED BALL BEARING 6204      |                                | 1.00     |
| 7   | 90133032000 | WASHER 20X33X0,5               |                                | 1.00     |
| 8   | 90133006000 | DRIVE WHEEL 6. GEAR            |                                | 1.00     |
| 9   | 90133001003 | BUSHING                        |                                | 1.00     |
| 10  | 90633033000 | WASHER                         |                                | 2.00     |
| 11  | J471020122  | CIRCLIP 20X1,2                 |                                | 2.00     |
| 12  | 90133003000 | DRIVE WHEEL 3. G./4.G.         |                                | 1.00     |
| 14  | 90133005000 | DRIVE WHEEL 5. GEAR            |                                | 1.00     |
| 15  | 90633002000 | DRIVE WHEEL 2. GEAR            |                                | 1.00     |
| 16  | 90633001004 | THRUST WASHER                  |                                | 1.00     |
| 17  | J618152114  | NEEDLE BEAR. HK1514RS 15X21X14 |                                | 1.00     |