



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|-------------|--------------------------------|--------------------------------|----------|
| 1 | 90633001000 | MAIN SHAFT CPL. | | 1.00 |
| 3 | 90133001011 | COLLAR BUSHING MAIN SHAFT | for clutch hub w/o brass inlay | 1.00 |
| 4 | J005060123 | FLAT HEAD SCREW M6X12 PH | | 1.00 |
| 5 | 90130004002 | LOCK WASHER F.BEARING DRIVE | | 1.00 |
| 6 | J625062040 | GROOVED BALL BEARING 6204 | | 1.00 |
| 7 | 90133032000 | WASHER 20X33X0,5 | | 1.00 |
| 8 | 90133006000 | DRIVE WHEEL 6. GEAR | | 1.00 |
| 9 | 90133001003 | BUSHING | | 1.00 |
| 10 | 90633033000 | WASHER | | 2.00 |
| 11 | J471020122 | CIRCLIP 20X1,2 | | 2.00 |
| 12 | 90133003000 | DRIVE WHEEL 3. G./4.G. | | 1.00 |
| 14 | 90133005000 | DRIVE WHEEL 5. GEAR | | 1.00 |
| 15 | 90633002000 | DRIVE WHEEL 2. GEAR | | 1.00 |
| 16 | 90633001004 | THRUST WASHER | | 1.00 |
| 17 | J618152114 | NEEDLE BEAR. HK1514RS 15X21X14 | | 1.00 |