




| Pos | Part Number | Description                    | Additional Text   | Quantity |
|-----|-------------|--------------------------------|-------------------|----------|
| 2   | 54739005000 | FLYWHEEL KOKUSAN 2K-1/2K-4 '97 | 125 SX            | 1.00     |
| 5   | 54839004000 | STATOR KOKUSAN 2K-1 2006       |                   | 1.00     |
| 10  | 47039090000 | SPARK PLUG CAP NGK REINFORC.04 |                   | 1.00     |
| 12  | 50231012000 | SEALING CUP FOR SPARK PLUG     | 200               | 1.00     |
| 13  | 51539093000 | SPARK PLUG                     |                   | 1.00     |
| 16  | 59039006000 | IGNITIONCOIL "IG5128"          | ONLY FOR SIX DAYS | 1.00     |
| 31* | 51539031600 | CDI UNIT 150 SX 2015           |                   | 1.00     |
| 32  | 54839032200 | WIRING HARNESS FOR CDI 2-ST.07 |                   | 1.00     |
| 36  | 58214069051 | rubber grommet 16x10.8x3       |                   | 1.00     |
| 37  | 0081645121  | EJOT DELTA PT SCREW 45X12-Z    |                   | 2.00     |
| 39  | 51511094100 | ELECTRIC CASE                  |                   | 1.00     |
| 40  | 0025050166  | HH collar screw M5x16 TX30     |                   | 3.00     |
| 43  | 0025060166  | HH collar screw M6x16 TX30     |                   | 2.00     |

\* = New part