



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|-------------|--------------------------------|-----------------|----------|
| 1 | 0625062062 | BALL BEARING 6206 C3 J1 NSK | | 1.00 |
| 2 | 0405263113 | NEEDLE BEAR. K 26-31-13 | | 1.00 |
| 3 | 60033005000 | IDLER GEAR 5.G "600 5P24" | | 1.00 |
| 4 | 60033042000 | STOP DISK 28,3/35,75/1,5 | | 1.00 |
| 5 | 0417280150 | LOCK RING DIN5417-WS28 | | 1.00 |
| 6 | 60033003000 | SLIDING G 3/4.G "600 34P18/20" | | 1.00 |
| 7 | 60033041000 | STOP DISK 22,2/30,2/1,5 | | 1.00 |
| 8 | 0405222613 | NEEDLE BEAR. K 22X26X13 TN | | 1.00 |
| 9 | 60033006000 | IDLER GEAR 6.G "600 6P27" | | 1.00 |
| 10 | 60033002100 | SOLID GEAR 2.G. "600 2P15-1" | | 1.00 |
| 11 | 60033040015 | STOP DISK 20,2X28X1,5 | | 1.00 |
| 11 | 60033040016 | STOP DISK 20,2/28/1,6 | | 1.00 |
| 11 | 60033040017 | STOP DISK 20,2/28/1,7 | | 1.00 |
| 11 | 60033040018 | STOP DISK 20,2/28/1,8 | | 1.00 |
| 11 | 60033040019 | STOP DISK 20,2/28/1,9 | | 1.00 |
| 11 | 60033040020 | STOP DISK 20,2/28/2,0 | | 1.00 |
| 11 | 60033040021 | STOP DISK 20,2/28/2,1 | | 1.00 |
| 11 | 60033040022 | STOP DISK 20,2/28/2,2 | | 1.00 |
| 12 | 60033001000 | MAIN SHAFT 12-T 03 | | 1.00 |
| 13 | 0618091312 | NEEDLE BUSH HK0912 9/13/12 03 | | 1.00 |
| 14 | 0625062040 | BALL BEARING 6204 DU J1 C3 | | 1.00 |