



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|-------------|-------------------------------|-----------------|----------|
| 1 | 0625062062 | BALL BEARING 6206 C3 J1 NSK | | 1.00 |
| 2 | 60333001000 | MAIN SHAFT 12T | | 1.00 |
| 3 | 0618091312 | NEEDLE BUSH HK0912 9/13/12 03 | | 1.00 |
| 4 | 0405263113 | NEEDLE BEAR. K 26-31-13 | | 1.00 |
| 5 | 60333005000 | IDLER GEAR 5. GEAR | | 1.00 |
| 6 | 61233042000 | STOP DISK 27,9/35,75/1,5 | | 1.00 |
| 7 | 0417270150 | LOCK RING SW 27 | | 1.00 |
| 8 | 60333003000 | SLIDING GEAR 3./4. GEAR | | 1.00 |
| 9 | 61233041000 | STOP DISK 22,2/30,2/1,5 | | 1.00 |
| 10 | 0405222613 | NEEDLE BEAR. K 22X26X13 TN | | 1.00 |

| | | | | |
|----|-------------|----------------------------|--|------|
| 11 | 60333006000 | IDLER GEAR 6. GEAR | | 1.00 |
| 12 | 60333002000 | SOLID GEAR 2ND GEAR | | 1.00 |
| 13 | 0625062040 | BALL BEARING 6204 DU J1 C3 | | 1.00 |
| 14 | 60033040015 | STOP DISK 20,2X28X1,5 | | 0.00 |
| 14 | 60033040016 | STOP DISK 20,2/28/1,6 | | 0.00 |
| 14 | 60033040017 | STOP DISK 20,2/28/1,7 | | 0.00 |
| 14 | 60033040018 | STOP DISK 20,2/28/1,8 | | 0.00 |
| 14 | 60033040019 | STOP DISK 20,2/28/1,9 | | 0.00 |
| 14 | 60033040020 | STOP DISK 20,2/28/2,0 | | 0.00 |
| 14 | 60033040021 | STOP DISK 20,2/28/2,1 | | 0.00 |
| 14 | 60033040022 | STOP DISK 20,2/28/2,2 | | 0.00 |