



| Pos | Part Number | Description                   | Additional Text | Quantity |
|-----|-------------|-------------------------------|-----------------|----------|
| 1   | 0625062062  | BALL BEARING 6206 C3 J1 NSK   |                 | 1.00     |
| 2   | 60333001000 | MAIN SHAFT 12T                |                 | 1.00     |
| 3   | 0618091312  | NEEDLE BUSH HK0912 9/13/12 03 |                 | 1.00     |
| 4   | 0405263113  | NEEDLE BEAR. K 26-31-13       |                 | 1.00     |
| 5   | 60333005000 | IDLER GEAR 5. GEAR            |                 | 1.00     |
| 6   | 61233042000 | STOP DISK 27,9/35,75/1,5      |                 | 1.00     |
| 7   | 0417270150  | LOCK RING SW 27               |                 | 1.00     |
| 8   | 60333003000 | SLIDING GEAR 3./4. GEAR       |                 | 1.00     |
| 9   | 61233041000 | STOP DISK 22,2/30,2/1,5       |                 | 1.00     |
| 10  | 0405222613  | NEEDLE BEAR. K 22X26X13 TN    |                 | 1.00     |

|    |             |                            |  |      |
|----|-------------|----------------------------|--|------|
| 11 | 60333006000 | IDLER GEAR 6. GEAR         |  | 1.00 |
| 12 | 60333002000 | SOLID GEAR 2ND GEAR        |  | 1.00 |
| 13 | 0625062040  | BALL BEARING 6204 DU J1 C3 |  | 1.00 |
| 14 | 60033040015 | STOP DISK 20,2X28X1,5      |  | 0.00 |
| 14 | 60033040016 | STOP DISK 20,2/28/1,6      |  | 0.00 |
| 14 | 60033040017 | STOP DISK 20,2/28/1,7      |  | 0.00 |
| 14 | 60033040018 | STOP DISK 20,2/28/1,8      |  | 0.00 |
| 14 | 60033040019 | STOP DISK 20,2/28/1,9      |  | 0.00 |
| 14 | 60033040020 | STOP DISK 20,2/28/2,0      |  | 0.00 |
| 14 | 60033040021 | STOP DISK 20,2/28/2,1      |  | 0.00 |
| 14 | 60033040022 | STOP DISK 20,2/28/2,2      |  | 0.00 |