



| Pos | Part Number | Description                    | Additional Text | Quantity |
|-----|-------------|--------------------------------|-----------------|----------|
| 1   | 76039006000 | STICK COIL                     |                 | 4.00     |
| 2   | 60439093000 | SPARK PLUG M12X1.25            |                 | 2.00     |
| 3   | 60439094000 | SPARK PLUG                     |                 | 2.00     |
| 4   | 60339035000 | SPECIAL SCREW M5X16            |                 | 2.00     |
| 5   | 59039034000 | pulse generator KOKUSAN 4K3-A/ |                 | 1.00     |
| 8   | 60439005000 | ROTOR CPL.                     |                 | 1.00     |
| 9   | 60039040020 | generator line bracket         |                 | 1.00     |
| 10  | 0025060256  | HH collar screw M6x25 TX30     |                 | 4.00     |
| 11* | 61230040100 | GASKET GENERATORCOVER          |                 | 1.00     |
| 12  | 49030090000 | DOWEL 9,8 X 7 X 10             | FS-E            | 2.00     |
| 13  | 60339004000 | STATOR                         |                 | 1.00     |

|    |               |                              |  |       |
|----|---------------|------------------------------|--|-------|
| 14 | 6023010214441 | IGNITION COVER WITH BEARINGS |  | 1.00  |
| 15 | 07700240251   | o-ring 24.00x2.50 Viton      |  | 1.00  |
| 16 | 6003009400030 | threaded plug M24x1.5 PA 6.6 |  | 1.00  |
| 18 | 60339003000   | special screw M12x1.5 WS15   |  | 1.00  |
| 20 | 0025060306    | HH collar screw M6x30 TX30   |  | 10.00 |
| 21 | 0025060356    | HH collar screw M6x35 TX30   |  | 2.00  |

\* = New part