




Pos	Part Number	Description	Additional Text	Quantity
1	76011075200	MAIN HARNESS		1.00
2	000700000BH	SPARE CONNECTOR BH 6-PINS	DIAGNOSTIC PORT	1.00
3	75011088010	FUSE 10A 07		0.00
3	75011088015	FUSE 15A 07		0.00
4	58011109125	FUSE 25 A		0.00
4	58011109115	FUSE 15 A		0.00
5	75011087050	RUBBER CASING FOR FUSE BOX		1.00
8	0024060206	HH collar screw M6x20 TX30		1.00
9	76011060100	DC HORN 12V		1.00
10	49007439000	CLAMP RSGU 15/12		1.00
11	78105081010	SCREW TORX M5X10		3.00
12	000700000HJ01	CAP FOR CONNECTOR 000700000HJ		1.00
13	61111018100	Temperatur sensor		1.00
15	76011057000	BRACKET F. FUSE BOX		1.00
17	69008021080	clip nut M5		2.00
20	44011076200	Cable tie 200/4.6mm black		0.00
21	60011093045	RUBBER CABLE TIE 45MM 03		0.00
28	76011094000	CABLE SUPPORT		1.00
29	76011093000	CABLE SUPPORT		2.00
33	76011048000	AMBIENT-AIR TEMP. SENSOR CABLE		1.00