



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|-------------|--------------------------------|-----------------|----------|
| 1 | 50314057000 | TUBO IN GOMMA RACC.RADIAT.SERB | | 1.00 |
| 2 | 50314065300 | SPEEDOMETER BOX FACOMSA 2000 | | 1.00 |
| 7 | 50314057050 | COLLAR NUT M12X1/WS17 H=5MM | | 1.00 |
| 8 | 31008060000 | rubber grommet D=8mm open | | 2.00 |
| 9 | 49111425000 | BULB 12V 1,2W (W2X4,6D) | | 3.00 |
| 10 | 0016050121 | SCREW FOR PLASTIC 50X12 | BLACK | 2.00 |
| 15 | 50314061000 | SPEEDOM.BRACKET 125-380 EGS'99 | | 1.00 |
| 17 | 0014060103 | HH COLLAR SCREW M 6X10 WS=8 | | 2.00 |
| 20 | 58414055200 | SPEEDOM.CABLE M12/M12 960MM'99 | | 1.00 |
| 21 | 50314050000 | SPEEDOMETER DRIVE 748220 (3.0) | 400/640 LC4-E | 1.00 |
| 23 | 50314053000 | DRIV.DOG F.SPEEDOM.DRIVE 2000 | | 1.00 |