




| Pos | Part Number | Description                    | Additional Text | Quantity |
|-----|-------------|--------------------------------|-----------------|----------|
| 1   | 58011180000 | ODOMETER                       |                 | 1.00     |
| 5   | 55011599000 | PULL SWITCH LOOSE              | IGNITION ON/OFF | 1.00     |
| 9   | 0015060123  | HH COLLAR SCREW M 6X12 WS=8    |                 | 2.00     |
| 10  | 54611120200 | SPEEDOMETER BRACKET VDO/ODO'95 |                 | 1.00     |
| 11  | 0125040003  | WASHER DIN0125-A 4,0           |                 | 2.00     |
| 12  | 0985040003  | SELF LOCKING NUT DIN0985-M 4   |                 | 2.00     |
| 20  | 58414055200 | SPEEDOM.CABLE M12/M12 960MM'99 |                 | 1.00     |

|    |             |                                |               |      |
|----|-------------|--------------------------------|---------------|------|
| 25 | 50314050000 | SPEEDOMETER DRIVE 748220 (3.0) | 400/640 LC4-E | 1.00 |
| 27 | 50314053000 | DRIV.DOG F.SPEEDOM.DRIVE 2000  |               | 1.00 |