



| Pos | Part Number | Description                    | Additional Text | Quantity |
|-----|-------------|--------------------------------|-----------------|----------|
| 4   | 49033031015 | STOP DISK 14,2X22X1,5          |                 | 1.00     |
| 5   | 50337005000 | SIDE COVER R/S '98             |                 | 1.00     |
| 6   | 50337006000 | GASKET SIDE COVER R/S          |                 | 1.00     |
| 7   | 50337007100 | SIDE COVER LEFT M10 2002       |                 | 1.00     |
| 8   | 50337008000 | GASKET SIDE COVER L/S          |                 | 1.00     |
| 9   | 50330022000 | ANGLE PIEC 90 DEGREE M10X1     |                 | 1.00     |
| 10  | 0770008020  | O-RING 8,00X2,00 NBR           |                 | 2.00     |
| 11  | 0015050123  | HH COLLAR SCREW M 5X12 WS=8    |                 | 8.00     |
| 12  | 0402051600  | NEEDLE ROL. DIN5402 NRB 5X15,8 |                 | 3.00     |
| 13  | 0015050163  | HH COLLAR SCREW M 5X16 WS=8    |                 | 2.00     |

|     |             |                                |              |      |
|-----|-------------|--------------------------------|--------------|------|
| 14* | 50332095200 | TUBE RUBBER 6X9 DVOH 200MM     |              | 1.00 |
| 15  | 0603262322  | CU-SEAL RING DIN7603-26X32X2   |              | 1.00 |
| 16  | 50337050064 | WASHER 5,2 X 12 X 3            |              | 1.00 |
| 17  | 0015060103  | HH COLLAR SCREW M 6X10 WS=8    | FC           | 1.00 |
| 18  | 52337018044 | ECCENTRIC FOR CRANKBOLT 200'98 |              | 1.00 |
| 19  | 52337019000 | CRANK BOLT F.CONTROL FL.200'98 |              | 1.00 |
| 20  | 52337020000 | CONTROL FLAP 200 '98           |              | 1.00 |
| 21  | 51237021000 | AXLE FOR CONTRIL FLAP 01       |              | 2.00 |
| 22  | 0603061001  | CU-SEAL RING DIN7603-6X10X1    |              | 2.00 |
| 23  | 0625006087  | Grooved ball bearing 608 2RS C |              | 4.00 |
| 24  | 0472022100  | CIRCLIP DIN0472-22X1           |              | 1.00 |
| 25  | 0093821606  | WASHER DIN2093-8,2X16X0,6      |              | 2.00 |
| 26  | 50337050063 | SPACER BUSHING 8X12X2,3        |              | 1.00 |
| 28  | 00099300011 | O-RINGSTRING 4MM NBR 70 PER/M  |              | 0.01 |
| 29  | 0770160030  | O-RING 16,00X3,00 NBR 70       |              | 1.00 |
| 30  | 52337030000 | SHEET METAL GUIDE 3MM 200'98   |              | 1.00 |
| 35  | 50337035000 | CLOSING COVER '98              |              | 1.00 |
| 36  | 50337035050 | CLOSING COVER GASKET 1MM       |              | 1.00 |
| 50  | 52337050044 | CENTRIFUGAL TIMER CPL. 200'98  | 200 MXC, EXC | 1.00 |
| 51  | 50337050062 | BUSHING HOLDER M 26X1 '98      |              | 1.00 |
| 52  | 50337050061 | CLOSING NUT M 26X1 WS=30       |              | 1.00 |
| 57  | 50337057000 | CONTROL LEVER 125/200'98       |              | 1.00 |
| 59  | 50337059000 | CONTROL SHAFT M 6 WS=10 '98    |              | 1.00 |
| 61  | 52337061144 | CONTROL SHAFT CPL.L/S 200 2001 |              | 1.00 |
| 62  | 52337062144 | CONTROL SHAFT CPL.R/S 200 2001 |              | 1.00 |
| 64  | 0015060123  | HH COLLAR SCREW M 6X12 WS=8    |              | 3.00 |
| 66  | 50337066000 | LEVER F. CONTROL SEGMENT '98   |              | 1.00 |
| 67  | 52337067000 | CONTROL SHAFT SEGMENT 200'98   |              | 1.00 |
| 70  | 50335054026 | DRIVE WHEEL 26-T 125/200'98    |              | 1.00 |
| 71  | 50335056000 | BUSHING SUPPORT WATER PUMP '98 |              | 1.00 |
| 72  | 50337072000 | ROLLER GUIDE 5X6,1X8X4 '98     |              | 6.00 |
| 73  | 0760082472  | SHAFT SEAL RING 8X24X7 A DUO   |              | 1.00 |
| 74  | 0625060001  | BALL BEARING 6000/C3           |              | 1.00 |
| 75  | 0770049025  | O-RING 49,00X2,50 NBR          |              | 1.00 |
| 76  | 50335054050 | WATER PUMP SHAFT 125/200'98    |              | 1.00 |
| 77  | 0349000050  | WASHER DIN7349-5X15X2          |              | 1.00 |
| 78  | 54635005000 | WATER PUMP WHEEL               |              | 1.00 |
| 79  | 50337079000 | LOCK METAL SHEET 2MM '98       |              | 2.00 |

\* = New part