



Pos	Part Number	Description	Additional Text	Quantity
0	58311121100	FLASHER SUPPORT R/S DUKE'94		1.00
1	58311065100	* TACHOMETER 10000 RPM '96		1.00
2	58311065050	WIRE FOR TACHOMETER		1.00
3	58311029100	INSTRUMENT LIGHTS 12V		2.00
4	58311053000	HEXAGON NUT M5X15 WS=8		4.00
5	58311088100	REDUCTION RUBBER		4.00
6	58311188000	*SPEEDOMETER CABLEM12/12 845MM		1.00
7	49111425000	BULB 12V 1,2W (W2X4,6D)		4.00
8	58311068100	* SPEEDOMETER KMH DUKE'94		1.00
8	58311068300	SPEEDOMETER MILES DUKE'96		1.00
9	58311052060	TRIPMETER RESET KNOB		1.00
10	0984020051	OVAL H.SCREW DIN7984-M 2X 5		1.00
11	58301098100	PLASTIC CAP 3/8" 261		1.00
12	58311054000	FOAM RUBBER RING 81x97x10		2.00
13	58312112000	* RUBBER RING 16 X 22 X 7		1.00
15	58311051000	INSTRUMENTS BRACKET		1.00

16	58311051050	BRACKET FOR INSTRUMENT BRACKET		1.00
17	54335031200	RUBBER GROMMET 20X25-M6X10 (2)		1.00
18	44012057000	SILENTBL.20X20-M6X15(2)45SHORE		2.00
19	0125060003	WASHER DIN0125-A 6,4		0.00
20	0797060003	TOOTH LOCK WASH. DIN6797-A 6,4		0.00
21	0934060003	Hex. nut DIN 934 M6		6.00
22	58311021100	FLASHER SUPPORT L/S DUKE'94		1.00
23	0912060123	AH SCREW DIN0912-M 6X12		2.00
30	58311066044	* LOCK SET CPL. DUKE'94		1.00
33	0985040123	FLAT HEAD SCREW DIN7985-M 4X12		2.00
40*	58011021200	HIGH BEAM INDICATOR LIGHT BLUE		1.00
41*	58011023200	NEUTRAL INDICATOR LIGHT GREEN		1.00
42*	58011022200	TEMPERATURE WARNING LIGHT RED		1.00
43*	58011024200	FLASHER INDICATOR LIGHT GREEN		1.00
44*	58011022300	OIL WARNING LIGHT RED		1.00
45*	58411078000	INDICATOR LIGHT WIRING '96		1.00

\* = New part