



Pos	Part Number	Description	Additional Text	Quantity
0	44011076200	CABLE TIE 200/3,6MM BLACK		0.00
1*	58714075000	TACHOMETER DUKE '99		1.00
2	58212085000	TRIPMASTER IMO-100R CPL. '97		1.00
4	58212085050	DISPLAY LENS FOR TRIPM.ADV.'97		1.00
5	58212085051	KEYBOARD FOIL F.TRIPM. ADV.'97		1.00
6	0985040003	SELF LOCKING NUT DIN0985-M 4		8.00
7	0021040003	WASHER DIN9021-A 4,3		4.00
8	58212085052	RUBBER GROMMET 15X8-M4X10 (2)		4.00
9*	58211001063	FOAM 4X9MM PER METER		0.00
11	49111425000	BULB 12V 1,2W (W2X4,6D)		3.00
12*	31008008000	RUBBER GROMMIT BLACK		2.00

13*	0134070003	WASHER DIN0134- 7,4		2.00
14*	0934050003	HEXAGON NUT DIN0934-M 5		2.00
16*	58311054000	FOAM RUBBER RING 81x97x10		1.00
20*	58214070100	COCKPIT COVER ADVENTURE '01		1.00
21*	58214070150	BORDER PROTEC. ADVENTURE 2002		0.00
23	0587060001	HH CAP NUT DIN1587-M 6 BLACK		2.00
24	56032005100	WASHER 6X17X1,5 BLACK		2.00
25*	58211078100	WIRING HAR. F. CONTROLS ADV.01		1.00
27	58212083000	CONTRAST POTENTIOMETER ADV.'97		1.00
30	58411066000	IGNITION LOCK W.LIGHTSWITCH 98	4 SWITCH POSITIONS	1.00
31*	0912080103	AH SCREW DIN912 M8X10		1.00
32	58212084000	SENSOR CABLE CPL. ADVENTURE'97		1.00
33	0985040123	FLAT HEAD SCREW DIN7985-M 4X12		2.00
35*	58214050151	BRACKET F.SENSOR ADVENTURE 01		1.00
36*	58214069050	SENSOR MAGNET ADVENTURE 01	625 SC SUPERMOTO	1.00
38	55011022000	CLAMP D=6/8MM, BLACK		0.00
39	44011076100	CABLE TIE 100/2,5MM BLACK		0.00
40*	58011021300	H.BEAM INDICATOR LIGHT BLUE'98	EXC EU+AUS	1.00
41*	58011023300	NEUTRAL INDIC. LIGHT GREEN '98		1.00
42*	58011022400	TEMPERATURE WARN. LIGHT RED'98		1.00
43*	58011024300	FLASHER INDICAT.LIGHT GREEN'98	EXC EU+AUS	1.00
44*	0799070000	TAB WASHER DIN6799-RS 7,0	625 SC SUPERMOTO	1.00

\* = New part