



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|-------------|--------------------------------|-----------------|----------|
| 2 | 77304030044 | SWINGARM CPL. 07 | | 1.00 |
| 3 | 77304066000 | CHAIN SLIDING PROTECTION | | 1.00 |
| 4 | 77304066050 | chain slider bushing | | 2.00 |
| 5 | 0009050103 | SPECIAL SCREW M 5,0X10 | | 2.00 |
| 6 | 77313047000 | BRAKE HOSE GUIDE LOWER 07 | | 1.00 |
| 7 | 0015060103 | HH COLLAR SCREW M 6X10 WS=8 | FC | 2.00 |
| 8 | 54804034000 | Bucket f. shaft seal ring 03 | | 4.00 |
| 9 | 0760253270 | radial shaft seal 25x32x7 | | 6.00 |
| 10 | 54804032000 | BUSHING SLEEVE F. SWING ARM 03 | | 2.00 |
| 11 | 58033097000 | NEEDLE BEARING HK 2216 | | 4.00 |
| 12 | 54603036000 | STOP DISK 22,2X31,7X1 | | 2.00 |
| 14 | 77304070100 | CHAIN GUIDE REAR CPL. 07 | | 1.00 |
| 15 | 0015060203 | HH COLLAR SCREW M 6X20 WS=8 | | 1.00 |
| 16 | 0015060453 | HH COLLAR SCREW M 6X45 WS=8 | 525 SMR | 1.00 |
| 17 | 77304070130 | BUSH. F. CHAIN FAIL. PROT. 07 | | 1.00 |
| 18 | 50304090044 | PIVOT BEARING+BUSH. PDS '99 | | 1.00 |
| 19 | 50329000044 | TOOL BEARING MOUNTING PDS | | 1.00 |

| | | | | |
|----|-------------|-------------------------------|------------------|------|
| 20 | 77304070030 | INSERTION NUT F. CHAIN GUIDE | | 1.00 |
| 25 | 77304037000 | SWINGARM BOLT M16X1,5 07 | | 1.00 |
| 26 | 54804038000 | Nut with flange M16X1,5 WS=19 | | 1.00 |
| 27 | 58404041100 | CLOSING COVER ROUND 03 | EXC+MXC SWINGARM | 4.00 |
| 28 | 77304066010 | CHAIN GUARD CPL. 07-11 | | 1.00 |
| 29 | 54603055051 | PRESS IN NUT M6 STEEL ZINC | | 1.00 |