



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|-------------|--------------------------------|---------------------------|----------|
| 1 | 63642031044 | ABS modul filled | | 1.00 |
| 2 | 64142040000 | holder ABS module | | 1.00 |
| 3 | 59001092050 | SPECIAL SCREW M6X12,5 WS=8 | | 2.00 |
| 4 | 61342041000 | Collar bushing 6.5X9X18X8.5 | | 3.00 |
| 5 | 69014017000 | SPECIAL SCREW M6X18 ISA30 08 | | 3.00 |
| 6 | 63642003000 | Brake line, brake caliper, fro | | 1.00 |
| 7 | 0025060166 | HH collar screw M6x16 TX30 | | 1.00 |
| 8 | 60111094100 | BAR SPACER 4/7 BLACK | | 6.00 |
| 10 | 0603100141 | sealing ring DIN 7603 10x14x1 | ONLY FOR LC4 ADVENTURE | 18.00 |
| 11 | 63642003070 | Brake line guide | | 1.00 |
| 12 | 69008021160 | special screw M5x12 | | 2.00 |
| 13 | 90142125000 | ABS SENSOR | | 1.00 |

| | | | | |
|----|--------------|--------------------------------|--|------|
| 14 | 014580060166 | Cap head bold ISO 14580 M6x16 | | 2.00 |
| 15 | 63642001000 | Brake line, front master cylin | | 1.00 |
| 16 | 62113020100 | banjo bolt M10x1x19.5 | | 7.00 |
| 17 | 64111051100 | Brake light switch | | 1.00 |
| 18 | 64142002000 | Hydraulic rear Brake Master Cy | | 1.00 |
| 19 | 62111051000 | BRAKE LIGHT SWITCH REAR | | 1.00 |
| 20 | 63642004000 | Brake line, rear brake caliper | | 1.00 |
| 21 | 54813026100 | CABLE SUPPORT 10/4MM 2014 | | 1.00 |
| 22 | 76042125000 | ABS-SENSOR | | 1.00 |
| 23 | 61542090000 | Angle sensor | | 1.00 |
| 24 | 64142090050 | Lean Angle Sensor Bracket | | 1.00 |
| 25 | 62142041000 | DAMP. COMPONENT ABS MODUL | | 1.00 |
| 26 | 69014015000 | collar bushing 6.1x9.2x15x8.5x | | 3.00 |
| 27 | 69014017000 | SPECIAL SCREW M6X18 ISA30 08 | | 5.00 |