




| Pos | Part Number | Description                    | Additional Text | Quantity |
|-----|-------------|--------------------------------|-----------------|----------|
| 1*  | 77033170044 | KICK STARTER CPL.              |                 | 1.00     |
| 2   | 0019080206S | FLAT HEAD SCREW M. ISA45 M8X20 |                 | 1.00     |
| 3   | 54633037000 | WASHER 8MM GALVANIZED          |                 | 1.00     |
| 4   | 0760193070  | SHAFT SEAL RING 19X30X7 B      |                 | 1.00     |
| 7   | 0471170010  | CIRCLIP DIN0471-17X1           |                 | 1.00     |
| 8   | 0471190120  | CIRCLIP DIN0471-19X1,2         |                 | 1.00     |
| 13  | 54633074000 | SPRING HANGER                  |                 | 1.00     |
| 17  | 0405222610  | NEEDLE BEARING K 22X26X10 A    |                 | 1.00     |
| 19  | 59033069000 | BUMP PART                      |                 | 1.00     |
| 24  | 54833024000 | INTERMEDIATE GEAR 2003         |                 | 1.00     |
| 25  | 54633025000 | KICKSTARTER SPRING             |                 | 1.00     |
| 26  | 54633026000 | DRIVING HUB                    |                 | 1.00     |
| 28  | 58033028000 | RATCHET GEAR SPRING 1,2 MM     |                 | 1.00     |
| 31  | 58033031000 | STOP DISK 22,2 X 30 X 1,5      |                 | 1.00     |
| 32  | 59033080000 | Shim 20x31.9x1                 |                 | 1.00     |
| 33  | 54633090000 | STOP DISK 17,2X25X1            |                 | 1.00     |
| 34  | 0988172405  | SHIM WASHER DIN0988-17X24X0,5  |                 | 1.00     |
| 50* | 59033050100 | KICKSTARTER SHAFT              |                 | 1.00     |

|    |             |                             |    |      |
|----|-------------|-----------------------------|----|------|
| 51 | 54833051034 | KICKSTARTER GEAR 34-T 03    |    | 1.00 |
| 52 | 59033052000 | RATCHET GEAR KICKSTARTER    |    | 1.00 |
| 60 | 0015060103  | HH COLLAR SCREW M 6X10 WS=8 | FC | 1.00 |
| 61 | 0015060203  | HH COLLAR SCREW M 6X20 WS=8 |    | 2.00 |

\* = New part