



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|-------------|--------------------------------|-----------------|----------|
| 1 | 46181414S1 | upper part cpl. | | 1.00 |
| 2 | 46181138 | Bearing bush 14x15,03/18,5/24, | | 4.00 |
| 3 | 50180095 | HS cylinder-head screw R1/8 I8 | | 1.00 |
| 4 | 36120151S | PLUG SCREW M5X6 CPL. | | 1.00 |
| 5 | 46810893 | O-ring 5,28x1,78 NBR70 black | | 1.00 |
| 6 | 46811208 | Rubber cap do not open 22x5,5 | | 1.00 |
| 7 | 50181101S52 | Compression cpl. | | 1.00 |
| 8 | 46810010 | Round-wire snap ring 49x1,5 | | 1.00 |
| 9 | 46181525S1 | lower part cpl. | | 1.00 |
| 10 | 15000M03S1 | PA with locking ring | | 1.00 |

| | | | | |
|----|-----------------|--------------------------------|--|------|
| 11 | 91010365 | Mainspring (59)160-198,5 dampe | | 1.00 |
| 11 | S80980000500020 | Mainspring (59)150-198,5 dampe | | 0.00 |
| 11 | S80980000600020 | Mainspring (59)170-198,5 dampe | | 0.00 |
| 12 | 52000214 | Sticker set XPLOR PDS 90x40 | | 1.00 |
| 13 | RP10040T | Repair kit spring retainer sho | | 0.00 |
| 14 | RP10013 | Repair kit ADV. R | | 0.00 |
| 15 | R12012T | Ball joint bearing kit top 12m | | 0.00 |
| 98 | 50180751S1 | SHOCK ABSORBER FLUID 5 LT | | 0.00 |