



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|---------------|------------------------------|-----------------|----------|
| 1 | 7503000210041 | IGNITION COVER | | 1.00 |
| 2 | 49030090000 | DOWEL 9,8 X 7 X 10 | FS-E | 2.00 |
| 3 | 60039040020 | generator line bracket | | 1.00 |
| 4 | 07700240251 | o-ring 24.00x2.50 Viton | | 1.00 |
| 5 | 6003009400030 | threaded plug M24x1.5 PA 6.6 | | 1.00 |
| 6 | 75030040000 | IGNITI.COVER GASKET 07 | | 1.00 |
| 7 | 75039004200 | Stator | | 1.00 |
| 8 | 76036075050 | INSET | | 2.00 |

| | | | | |
|----|-------------|-------------------------------|--|------|
| 9 | 75039005300 | Rotor | | 1.00 |
| 10 | 0025060166 | HH collar screw M6x16 TX30 | | 2.00 |
| 11 | 76636075000 | STICKCOIL HOLDER | | 1.00 |
| 12 | 76039006000 | STICK COIL | | 2.00 |
| 14 | 60439093000 | SPARK PLUG M12X1.25 | | 1.00 |
| 15 | 0025060256 | HH collar screw M6x25 TX30 | | 4.00 |
| 16 | 0025060306 | HH collar screw M6x30 TX30 | | 2.00 |
| 17 | 75039034000 | PULSER COIL | | 1.00 |
| 18 | 59009062016 | SPECIAL SCREW M6X16 WS=8 10.9 | | 2.00 |
| 19 | 60439094000 | SPARK PLUG | | 1.00 |
| 20 | 0025060256S | SK-BUNDSCHRAUBE M6X25 ISA30 | | 1.00 |
| 21 | 0025060306S | HH collar screw M6x30 TX30 | | 3.00 |