





ACHTUNG / ATTENTION

Für den Regler 6 wird das Kabel 8 benötigt

For the regulator 6 the harness 8 is required



Pos	Part Number	Description	Additional Text	Quantity
1	76111075000	Main wiring harness		1.00
2	76911076000	Rear part, wiring harness		1.00
3	75011088010	FUSE 10A 07		0.00
4	75011088015	FUSE 15A 07		0.00
5	75011087050	RUBBER CASING FOR FUSE BOX		1.00
6	60311034000	VOLTAGE REGULATOR		1.00
7	54603048100	clip nut M6		2.00
8	76111075010	Wiring harness, voltage regula		1.00
9	0025060206S	HH collar screw M6x20 TX30		2.00
10	0985060003	Self lock. nut DIN985-M6-A2		1.00
11	44011076140	CABLE TIE 140/2,5MM BLACK		0.00

11	44011076200	Cable tie 200/4.6mm black		0.00
11	44011076305	CABLE TIE 300/4,8MM BLACK		0.00
12	60011093045	RUBBER CABLE TIE 45MM 03		0.00
13	58411096100	DIODE S3H-15 97		3.00
14	64111060033	Direct current horn complete		1.00
15	000700000BH	SPARE CONNECTOR BH 6-PINS	DIAGNOSTIC PORT	1.00
16	61434051000	Shift shaft sensor		1.00
17	76834052000	Quickshifter sensor cover		1.00
18	000700000OE001	dummy connector OE 33-Pins		1.00
19	61011055045	EDGE PROTECTOR L=45MM 05		1.00
34	014580050203S	Cap hd. screw DIN14580 M5x20 P		2.00
35	78003123070	Spacing tube spring retaining		2.00