



Pos	Part Number	Description	Additional Text	Quantity
1	46181107	Distance bush 10x15/17/24,5x10		4.00
2	R12012T	Ball joint bearing kit top 12m		0.00
3	40140359	HS lock screw M10x1 l8 black A		1.00
4	50180100	O-ring 8x1,5 Viton75 green		1.00
5	36120151S	PLUG SCREW M5X6 CPL.		1.00
6	46810893	O-ring 5,28x1,78 NBR70 black		1.00
7	46811208	Rubber cap do not open 22x5,5		1.00
8	70181037S2	Compression cpl.		1.00
9	70181036S	Compression cpl.		1.00
10	50180217	O-ring 27x1,5 Viton70 green IS		2.00
11	70181049S	Adjustment screw HS rebound M2		1.00
12	46810811	O-ring 17x2 70 Sh NBR black		1.00
13	15000M02S2	PA cpl. KTM RC8C		1.00
14	46180737	Zwischenring spring 59x71,5x1		1.00

15	91010382	main spring (59) 68-130.0 shoc		0.00
15	91010383	main spring (59) 70-130.0 shoc		0.00
15	91010384	main spring (59) 72-130.0 shoc		0.00
15	91010385	Mainspring (59) 74-130.0 silen		0.00
15	91010386	Mainspring (59) 76-130.0 shock		0.00
15	91010387	main spring (59) 78-130.0 shoc		0.00
15	91010388	main spring (59) 80-130.0 shoc		0.00
15	91010389	main spring (59) 82-130.0 shoc		0.00
15	91010390	main spring (59) 84-130.0 shoc		1.00
15	91010391	main spring (59) 86-130.0 shoc		0.00
15	91010392	main spring (59) 88-130.0 shoc		0.00
15	91010393	main spring (59) 90-130.0 shoc		0.00
15	91010394	main spring (59) 92-130.0 shoc		0.00
15	91010395	main spring (59) 94-130.0 shoc		0.00
15	91010396	main spring (59) 96-130.0 shoc		0.00
15	91010397	main spring (59) 98-130.0 shoc		0.00
15	91010398	main spring (59) 100-130.0 sho		0.00
16	46180423	Spring retainer 30x58x-3		1.00
17	52000262	Sticker APEX PRO 75x40		1.00
99	RP10041	repair kit shock KTM RC8C		1.00