


#9 ENTHALTEN IM DICHTSATZ MOTOR KPL.
INCLUDED IN GASKET-SET ENGINE CPL.



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|---------------|--------------------------------|-----------------|----------|
| 1 | 60039006000 | STICK COIL 03 | | 2.00 |
| 2 | 61239093200 | SPARK PLUG M12X1,25 08 | | 2.00 |
| 3 | 60039040020 | generator line bracket | | 1.00 |
| 4 | 0025050166 | HH collar screw M5x16 TX30 | | 2.00 |
| 5 | 59039034000 | pulse generator KOKUSAN 4K3-A/ | | 1.00 |
| 8 | 61239005000 | FLYWHEEL CPL. 08 | | 1.00 |
| 10 | 0025060256 | HH collar screw M6x25 TX30 | | 3.00 |
| 11 | 61230040000 | IGNITION COVER GASKET 08 | | 1.00 |
| 12 | 49030090000 | DOWEL 9,8 X 7 X 10 | FS-E | 2.00 |
| 13 | 61239004000 | STATOR | | 1.00 |
| 14 | 6123000204441 | IGNITION COVER WITH BEARING | | 1.00 |
| 15 | 0770024025 | O-RING 24X2,5 NBR | | 1.00 |
| 16 | 6003009400030 | threaded plug M24x1.5 PA 6.6 | | 1.00 |
| 17 | 61239003050 | WASHER 12,5/25/3 | | 1.00 |
| 18 | 61239003000 | SCREW M12X1,5 | | 1.00 |
| 19 | 80030058060 | OIL JET "60" M4 | | 1.00 |
| 20 | 0025060306 | HH collar screw M6x30 TX30 | | 10.00 |
| 21 | 0025060356 | HH collar screw M6x35 TX30 | | 2.00 |