



Pos	Part Number	Description	Additional Text	Quantity
1	75011075000	WIRING HARNESS 07		1.00
2	000700000BH	SPARE CONNECTOR BH 6-PINS	DIAGNOSTIC PORT	1.00
3	75011088010	FUSE 10A 07		0.00
4	75011088015	FUSE 15A 07		0.00
5	75011087050	RUBBER CASING FOR FUSE BOX		1.00
6	75011083000	BRACKET FOR PLUGS 07		1.00
7	0081050121	EJOT PT screw K50x12	only for US and SixDays	3.00
8	0024060106	HH COLLAR SCREW M6X10 TX30		1.00
9	62511060000	DC HORN 05		1.00
10	49007439000	CLAMP RSGU 15/12		1.00
11	0912050103	AH SCREW DIN0912-M 5X10		1.00
20	44011076100	CABLE TIE 100/2,5MM BLACK		0.00
20	44011076200	CABLE TIE 200/3,6MM BLACK		0.00
20	44011076305	CABLE TIE 300/4,8MM BLACK		0.00
21	60011093075	RUBBER CABLE TIE 75MM 03		0.00
25	44611207200	FLASHER UNIT 97		1.00
26	58211031100	BRACKET FOR FLASHER RELAY		1.00

27	58411096100	DIODE S3H-15 97		1.00
33	75011047000	AMBIENT-AIR TEMP. SENSOR CABLE		1.00