




| Pos | Part Number   | Description             | Additional Text | Quantity |
|-----|---------------|-------------------------|-----------------|----------|
| 1   | 96211075000   | harness wiring          |                 | 1.00     |
| 2   | J900000602800 | SK-Bundschraube M6x28   |                 | 2.00     |
| 3   | 96311034000   | Regulator assembly      |                 | 1.00     |
| 4   | J900000801402 | Hex collar screw, M8x14 |                 | 1.00     |
| 5   | 96311060000   | Horn                    |                 | 1.00     |
| 6   | 96311061000   | Bracket horn            |                 | 1.00     |
| 7   | 28111096000   | Transil unit            |                 | 1.00     |
| 9   | 90508006001   | SOCKET HEAD BOLT M6X12  |                 | 2.00     |
| 11  | 96311083000   | Connector support       |                 | 1.00     |

|    |               |                                |  |      |
|----|---------------|--------------------------------|--|------|
| 12 | 96314086000   | UNIT CONNECTIVITY              |  | 1.00 |
| 13 | 96241088050   | BRACKET SENSOR ROLL OVER       |  | 1.00 |
| 14 | J650001801400 | grommet                        |  | 3.00 |
| 15 | J690000410000 | washer plain                   |  | 3.00 |
| 17 | J900000401600 | screw tapping pan cross dia 4. |  | 5.00 |
| 18 | 93011058000   | Starter relais                 |  | 1.00 |
| 19 | 93311058000   | Rubber damper starter relay    |  | 1.00 |
| 20 | 90611057000   | relay (interlock)              |  | 5.00 |
| 21 | 93511088000   | Fuse 10a                       |  | 9.00 |
| 21 | 90111088015   | Fuse 15A                       |  | 5.00 |
| 21 | 90111088030   | Fuse 30A                       |  | 1.00 |
| 21 | 90111088020   | Fuse 20A                       |  | 2.00 |
| 22 | 96311097000   | CABLE EARTH                    |  | 1.00 |
| 23 | 96311007000   | CABLE PUMP FUEL                |  | 1.00 |
| 24 | 96338091100   | CABLE SWITCH PRESSURE OIL      |  | 1.00 |
| 25 | 93811099000   | wiring harness temperatur sens |  | 1.00 |
| 26 | 90811059000   | STARTER CABLE                  |  | 1.00 |
| 29 | 93541088000   | rollover sensor                |  | 1.00 |
| 31 | 96311041000   | socket charger USB             |  | 1.00 |
| 32 | J025060122    | Hex collar screw M6X12         |  | 2.00 |
| 33 | 93803001022   | Cable tie                      |  | 3.00 |
| 34 | 96311058010   | cap relay starter              |  | 1.00 |
| 35 | 96311097002   | Busbar plate                   |  | 1.00 |
| 36 | J797060003    | TOOTHED WASHER M6              |  | 3.00 |
| 37 | J797100006    | washer toothed internal        |  | 1.00 |
| 99 | 96311081000   | Rear turn signal wiring harnes |  | 1.00 |
| 99 | 96311093000   | wiring harness BCCU            |  | 1.00 |
| 99 | 96311098000   | CABLE EARTH                    |  | 1.00 |