




Pos	Part Number	Description	Additional Text	Quantity
1	S454600029S0000	shock housing cpl.		1.00
2	36120151ST	PLUG SCREW M5X6 CPL.		1.00
3	S208600003000FB	O-ring 5,28x1,78 HNBR70 red		1.00
4	50180095	HS cylinder-head screw R1/8 18		1.00
5	RP10051T	Ball bearing kit		2.00
6	46181193	Pivotseal d.12X25,1 PDS		4.00
7	S012900000S1900	Compression Cpl		1.00
8	50180217	O-ring 27x1,5 Viton70 green IS		1.00
9	91010271S	SPRING (59) 215 30 N/MM		0.00
9	91010240S	Spring (59) 215 35 N/MM D=9,25		0.00
9	91010161S	SPRING (59) 215 40 N/MM D=9,5		0.00
9	91010201	Mainspring (59) 45-215 damper		1.00
9	91010080	Mainspring (59) 50-215 damper		0.00
9	91010170S	SPRING 55 N/MM		0.00
10	46181382S	Plastic Spring Retainer D46 cp		1.00

11	RP10005T	SPRING CUP SET PDS 17		1.00
12	S23902000000000	round-wire snap ring 49x1,75		1.00
13	46181351	Cover 46,12x15 h5,5 red		1.00
14	46181237	Rubber pad 17x48x55		1.00
15	S421800024S0000	bottom part M18x1 h54,5 cpl.		1.00
17	S614620000S0100	Seal support 46x28 cml.		1.00
18	46181659S	Nut PDS M10x1 h17,2 WAF19 cpl.		1.00
19	46181416	Piston 15,4x35,4x6		1.00
20	46181561	Bushing 10x17x21		1.00
21	46810474	Piston rod nut M12x1		1.00
22	46140031	Washer 12x24x4.5		1.00
23	S624600004S0000	piston 12x45,4x18 complete		1.00
24	S25120000700000	Rebound disc 12x36x9,8 h5,8		1.00
25	52000230	Sticker XACT 85 SX		1.00
98	50180751S1	SHOCK ABSORBER FLUID 5 LT		1.00
99	RP10064T	Repair kit suspension PDS 19		0.00