




Pos	Part Number	Description	Additional Text	Quantity
1	S454600000S0000	Shock absorber case cpl.		1.00
2	36120151ST	PLUG SCREW M5X6 CPL.		1.00
3	S208600003000FB	O-ring 5,28x1,78 HNBR70 red		1.00
4	50180095	HS cylinder-head screw R1/8 I8		1.00
5	RP10051T	Ball bearing kit		0.00
6	46181193	Pivotseal d.12X25,1 PDS		4.00
7	52000233	Sticker XPLOR PDS 90x40		1.00
8	S012900007S0600	Compression cpl		1.00
9	RP10044T	Repair kit adjuster DCC 2023		0.00
10	50180217	O-ring 27x1,5 Viton70 green IS		1.00
11	50180218	O-ring 25x1,5 Viton70		1.00

12	46181382S	Plastic Spring Retainer D46 cp		1.00
13	91010336	SHOCK SPRING L= 225 63 N/MM WH		0.00
13	91010337	Mainspring (59/61) 66-225 damp		0.00
13	91010338S	SPRING 225MM 69 N/MM		0.00
13	91010339	Mainspring (59/61) 72-225 damp		0.00
13	91010363	Mainspring (59/61) 75-225 damp		0.00
13	91010364	Mainspring (59/61) 78-225 damp		0.00
14	RP10052T	Spring plate repair kit		0.00
15	46181656	nut M10x1 h10,5 SW19		1.00
16	46181416	Piston 15,4x35,4x6		1.00
17	S71100000500000	Compression holder 10x48		1.00
18	46811258	Washer 12x24x2,5		1.00
19	S624600000S0000	Piston d46 cmpl.		1.00
20	46181194	Rebound disc 12x36x4 h0		1.00
21	S614620000S0100	Seal support 46x28 cmpl.		1.00
22	S23902000000000	round-wire snap ring 49x1,75		1.00
23	S409000004000FA	Cover 46.12x6.2 h14.2		1.00
24	S921800000000C1	Rubber pad 18x56x46 black		1.00
25	S421800001S0100	Piston rod cmpl.		1.00
98	50180751S1	SHOCK ABSORBER FLUID 5 LT		0.00
99	RP10053T	Repair kit shock absorber		0.00