



Pos	Part Number	Description	Additional Text	Quantity
1	S455000003S0100	Monoshock case M51x1 h19 with		1.00
2	S012900000S1400	Compression compl.		1.00
3	14460042	HS cylinder-head screw M5x20 D		1.00
4	50180095	HS cylinder-head screw R1/8 18		1.00
5	50180217	O-ring 27x1,5 Viton70 green IS		1.00
6	36120151S1	screw fill M5x6 cpl.		1.00
7	52000312	Sticker XACT LDS 80x29		1.00
8	S938100001S0000	SPRING SUPPORT		1.00
9	91210130	mainspring (62/65) 36-240 muff		0.00
9	91210131	mainspring (62/65) 39-240 muff		0.00
9	91210132	Main spring (62/65) 42-240,muf		0.00

9	91210133	Main spring (62/65) 45-240,muf	0.00
9	91210134	Main spring (62/65) 48-240,muf	0.00
9	91210135	mainspring (62/65) 51-245 muff	0.00
9	91210136	Mainspring (62) 54-250.0 shock	0.00
10	S828800000S01BQ	Spring seat 26,5x76,5x22,3 cpl	1.00
11	S208600003000FB	O-ring 5,28x1,78 HNBR70 red	1.00
12	50181207	Locking nut M12x1 h9 WAF19	1.00
13	50181344	Rebound disc 12x34x3,5 h0	1.00
14	S625000000S0000	Piston 12x49,4x18 cpl	1.00
15	50181091	Rebound disc 12x43x12,5 h8	1.00
16	50180603S7	Dichtungsträger 50x28 cpl.	1.00
17	50180126	Round-wire snap ring 53x1,75	1.00
18	50181349	Cap 50,12x16 h6	1.00
19	50181100	Rubber pad 18x58x46 black	1.00
20	S421800010S0100	Mounting fork with piston rod	1.00
21	RP10044T	Repair kit adjuster DCC 2023	0.00
22	46811205	Bush M10x12/15/13x9,5	1.00
23	S918100006S0000	adjuster rebound red cpl.	1.00
24	R15006	REPAIR KIT BEARINGS 07	0.00
25	50180218	O-ring 25x1,5 Viton70	1.00
98	50180751S1	SHOCK ABSORBER FLUID 5 LT	0.00
99	RP10043T	shock absorber rebuild kit	0.00