



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|---------------|--------------------------------|-----------------|----------|
| 1 | A61042031044 | ABS module filled | | 1.00 |
| 2 | A62442050000 | Brake line locking mechanism | | 1.00 |
| 3 | 61742040000C1 | Retaining bracket ABS modulato | | 1.00 |
| 4 | A62442001000 | Brake line brake cylinder | | 1.00 |
| 5 | 61742002000 | Brake line rear master cylinde | | 1.00 |
| 6 | A62442003000 | Brake line brake caliper front | | 1.00 |
| 7 | A62442004000 | Brake line rear brake caliper | | 1.00 |
| 8 | 61342046000 | Support ABS-pipe d7.5 | | 4.00 |
| 9 | 60311051000 | BRAKE LIGHT SWITCH REAR | | 1.00 |
| 10 | 0025060106 | HH collar screw M6x10 TX30 | | 2.00 |
| 11 | 0025060126 | HH collar screw M6x12 TX30 | | 2.00 |
| 12 | 0025060206 | HH collar screw M6x20 TX30 | | 2.00 |
| 13 | 0021060003 | Washer DIN9021-A 6.4 | ONLY USA | 2.00 |

| | | | | |
|----|-------------|-------------------------------|---------------------------|-------|
| 14 | 62142041100 | Damper 40 SHORE | | 3.00 |
| 15 | 61342041000 | Collar bushing 6.5X9X18X8.5 | | 3.00 |
| 16 | 0603100141 | sealing ring DIN 7603 10x14x1 | ONLY FOR LC4 ADVENTURE | 16.00 |
| 17 | 69013025000 | HOLLOW SCREW M10X1X19 SW12 | | 2.00 |
| 18 | 62113020100 | banjo bolt M10x1x19.5 | | 5.00 |
| 19 | 0024060206 | HH collar screw M6x20 TX30 | | 1.00 |
| 20 | 59032006050 | Spring retainer 6.2X12X18X5.2 | | 1.00 |
| 21 | 63711051100 | Brake light switch | | 1.00 |