



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|---------------|--------------------------------|---------------------------|----------|
| 1 | 63613080001C1 | Caliper without pad | | 1.00 |
| 2 | 63613075000C1 | Brake caliper support | | 1.00 |
| 3 | 54613311200 | RETAINING SPRING SET | | 1.00 |
| 4 | 54613218100 | CUP SET SHORT | | 1.00 |
| 5 | 61013020200 | BLEEDER SCREW WITH CAP | | 1.00 |
| 6 | 61013082000 | BOLT SET 05 | | 1.00 |
| 7 | 54613305200 | BRAKE PISTON 34MM | | 1.00 |
| 8 | 54613318200 | REPAIR KIT SEALING RINGS 34MM | | 1.00 |
| 9 | 50313090000 | BRAKE PAD REAR TOSHIBA TTH38GF | | 1.00 |
| 10 | 62113020100 | banjo bolt M10x1x19.5 | | 1.00 |
| 11 | 0603100141 | sealing ring DIN 7603 10x14x1 | ONLY FOR LC4 ADVENTURE | 2.00 |