



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|-------------|-----------------------------|-----------------|----------|
| 1* | 60111075333 | WIRING HARNESS 09 | | 1.00 |
| 2 | 61111057000 | RELAY CM1A-R-12V-H80 07 | | 4.00 |
| 3 | 58411096100 | DIODE S3H-15 97 | | 2.00 |
| 5 | 60111083000 | BRACKET FOR PLUGS 06 | | 1.00 |
| 6 | 0912050123 | AH SCREW DIN0912-M 5X12 | | 1.00 |
| 7 | 58011109105 | FUSE 5 A 2003 | | 0.00 |
| 8 | 58011109110 | Plug-in fuse, big 10A | | 0.00 |
| 9 | 58011109115 | FUSE 15 A | | 0.00 |
| 10 | 58011109125 | FUSE 25 A | | 0.00 |
| 11 | 58011109140 | FUSE 40 A | | 0.00 |
| 12 | 57013070400 | PVC CLAMP 17,4MM HEYCO 3381 | | 1.00 |

| | | | | |
|-----|-------------|-------------------------------|------------------|------|
| 13 | 0025050126 | HH collar screw M5x12 TX30 | | 3.00 |
| 14 | 44011076100 | CABLE TIE 100/2,5MM BLACK | | 0.00 |
| 14 | 44011076200 | CABLE TIE 200/3,6MM BLACK | | 0.00 |
| 14 | 44011076305 | CABLE TIE 300/4,8MM BLACK | | 0.00 |
| 15 | 49007439000 | CLAMP RSGU 15/12 | | 1.00 |
| 16 | 000700000BH | SPARE CONNECTOR BH 6-PINS | DIAGNOSTIC PORT | 1.00 |
| 17 | 0025060106 | HH collar screw M6x10 TX30 | | 4.00 |
| 18 | 60108017015 | RUBBER SLEEVE 22X18 MM 06 | | 1.00 |
| 19* | 60211022000 | HAZARD WARNING BUTTON | | 1.00 |
| 20 | 60011193000 | CABLE TIE WITH PLUG 03 | | 1.00 |
| 27* | 61111018000 | TEMPERATURE SENSOR 07 | | 1.00 |
| 30 | 60011092000 | OIL-PRESSURE SWITCH CABLE 03 | | 1.00 |
| 31 | 60011025000 | FLASHER CABLE FRONT 03 | | 2.00 |
| 34 | 60011060100 | DC HORN 12V 06 | | 1.00 |
| 36 | 60111076000 | WIRING HARNESS REAR 06 | | 1.00 |
| 37 | 58411049100 | CLUTCH SWITCH 03 | | 1.00 |
| 38 | 50311051100 | BRAKE LIGHT SWITCH REAR '98 | EXC EU+AUS | 1.00 |
| 39 | 60011050000 | BRAKE LIGHT SW. FRONT CPL. 03 | | 1.00 |
| 43 | 60011093045 | RUBBER CABLE TIE 45MM 03 | | 0.00 |
| 43 | 60011093060 | RUBBER CABLE TIE 60MM 03 | NOT FOR USA & CN | 0.00 |
| 43 | 60011093075 | RUBBER CABLE TIE 75MM 03 | | 0.00 |
| 44 | 61111020000 | STARTER INTERLOCK | | 1.00 |
| 50 | 60111079000 | WIRING HARNESS ABS 06 | | 1.00 |

* = New part