




| Pos | Part Number   | Description             | Additional Text | Quantity |
|-----|---------------|-------------------------|-----------------|----------|
| 1   | A60111175000  | HARNESS WIRING          |                 | 1.00     |
| 2   | J900000602800 | SK-Bundschrabe M6x28    |                 | 2.00     |
| 3   | A60111034000  | UNIT REGULATOR          |                 | 1.00     |
| 4   | J900000801402 | Hex collar screw, M8x14 |                 | 1.00     |
| 5   | 28111060000   | Horn                    |                 | 1.00     |
| 7   | 28111096000   | Transil unit            |                 | 1.00     |
| 9   | 90508006001   | SOCKET HEAD BOLT M6X12  |                 | 2.00     |
| 11  | 96311083000   | Connector support       |                 | 1.00     |
| 12  | 96314086000   | UNIT CONNECTIVITY       |                 | 1.00     |

|    |               |                                |  |      |
|----|---------------|--------------------------------|--|------|
| 13 | 96342091010   | 6-D sensor retaining bracket   |  | 1.00 |
| 14 | J650001801400 | grommet                        |  | 3.00 |
| 15 | J800000601000 | collar number plate mounting   |  | 3.00 |
| 16 | J900000601803 | Hex screw with collar M6x18    |  | 3.00 |
| 17 | J900000602202 | BOLT FLANGED M6X1              |  | 2.00 |
| 18 | 93011058000   | Starter relais                 |  | 1.00 |
| 19 | 93311058000   | Rubber damper starter relay    |  | 1.00 |
| 20 | 90611057000   | relay (interlock)              |  | 5.00 |
| 21 | 93511088000   | Fuse 10a                       |  | 7.00 |
| 21 | 90111088015   | Fuse 15A                       |  | 5.00 |
| 21 | 90111088030   | Fuse 30A                       |  | 1.00 |
| 21 | 90111088020   | Fuse 20A                       |  | 2.00 |
| 21 | 90111088025   | FUSE 25A                       |  | 2.00 |
| 22 | 96311097000   | CABLE EARTH                    |  | 1.00 |
| 23 | 96311007000   | CABLE PUMP FUEL                |  | 1.00 |
| 24 | 96338091000   | cable switch pressure oil      |  | 1.00 |
| 25 | 93811099000   | wiring harness temperatur sens |  | 1.00 |
| 26 | 96311059000   | Starter cable                  |  | 1.00 |
| 29 | 93541088000   | rollover sensor                |  | 1.00 |
| 30 | 95842092020   | cover sensor lean angle upper  |  | 1.00 |
| 31 | 96311041000   | socket charger USB             |  | 1.00 |
| 32 | J025060122    | Hex collar screw M6X12         |  | 2.00 |
| 33 | 93803001022   | Cable tie                      |  | 5.00 |
| 34 | 96311058010   | cap relay starter              |  | 1.00 |
| 35 | 96311097002   | Busbar plate                   |  | 1.00 |
| 36 | J797060003    | TOOTHED WASHER M6              |  | 3.00 |
| 37 | J797100006    | washer toothed internal        |  | 1.00 |
| 38 | 93035033010   | Washer                         |  | 2.00 |
| 39 | U6951130      | Cable ties 140/ 3.5mmm orange  |  | 0.00 |
| 39 | 90111093200   | BAND (LENGTH 200MM)            |  | 0.00 |
| 39 | 93011093300   | BAND 300MM                     |  | 0.00 |
| 40 | A60111076000  | CABLE REAR                     |  | 1.00 |
| 99 | 96311098000   | CABLE EARTH                    |  | 1.00 |