




Pos	Part Number	Description	Additional Text	Quantity
1	61111075133	WIRING HARNESS FRONT 990 SD 07		1.00
2	61011083000	BRACKET FOR PLUGS CPL. 05		1.00
3	49007439000	CLAMP RSGU 15/12		1.00
4	0912050103	AH SCREW DIN0912-M 5X10		1.00
5	61011083020	BRACKET FOR PLUGS COVER 05		1.00
6	60003088000	PLASTIC CAP FOR M6 03		4.00
7	44611207200	FLASHER UNIT 97		1.00
8	61011075020	DUMMY PLUG ALARM SYSTEM 05		1.00
9	61111057050	BRACKET RELAY 07		1.00
10	0016050121	SCREW FOR PLASTIC 50X12	BLACK	2.00
11	58411096100	DIODE S3H-15 97		2.00
12	61111057000	RELAY CM1A-R-12V-H80 07		4.00
13	75011088010	FUSE 10A 07		0.00

14	75011088015	FUSE 15A 07		0.00
16	000700000BH	SPARE CONNECTOR BH 6-PINS	DIAGNOSTIC PORT	1.00
17*	58411098100	CONTACT WASHER M6 VSV-K6		1.00
18*	0025060126	HH collar screw M6x12 TX30		1.00
19	61111079000	WIRING HARNESS FRONT 07		1.00
20	61011060000	DC HORN CPL. 05		1.00
21	0025060106	HH collar screw M6x10 TX30		2.00
22	60011092000	OIL-PRESSURE SWITCH CABLE 03		1.00
24	44011076100	CABLE TIE 100/2,5MM BLACK		0.00
24	44011076200	Cable tie 200/4.6mm black		0.00
24	44011076305	CABLE TIE 300/4,8MM BLACK		0.00
25	61011093000	WIRING HOLDER 05		1.00
26	58513001000	SPIRAL HOSE D=9MM PER METER	1 METER	0.00
27	75011087050	RUBBER CASING FOR FUSE BOX		1.00
28	61111020000	STARTER INTERLOCK		1.00
29	61111018000	TEMPERATURE SENSOR 07		1.00
30	58111076000	CABLE SUPPORT KHS NR.150-47610		0.00
31	61111041000	CABLE SUPPORT 07		0.00

* = New part