



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|----------------|----------------------------|-----------------|----------|
| 1 | A44030502044C1 | Generator Cover cpl. | | 1.00 |
| 2 | A44030040000 | Ignition cover gasket | | 1.00 |
| 3 | 55539104000 | Stator cmpl. | | 1.00 |
| 4 | A45039305000 | Rotor | | 1.00 |
| 5 | 0012050253S | Bolt DIN 6912 - M5x25 SS | | 3.00 |
| 6 | 55440126000 | BENDIX | | 1.00 |
| 7 | A44040201000 | Starter motor | | 1.00 |
| 8 | 0025060256 | HH collar screw M6x25 TX30 | | 2.00 |
| 9 | 55540031000 | Collar bushing | | 1.00 |
| 10 | 0025060206 | HH collar screw M6x20 TX30 | | 9.00 |
| 11 | 0025060306 | HH collar screw M6x30 TX30 | | 1.00 |

| | | | | |
|----|--------------|-------------------------------|----------|------|
| 12 | A44040040000 | Starter motor cover | | 1.00 |
| 14 | A45041031050 | Engine control unit rubber | | 1.00 |
| 15 | 55439140220 | Holding plate generator cable | | 1.00 |
| 16 | 0402040980 | Needle roll.DIN5402 NRB 4X9.8 | | 2.00 |
| 18 | 55539034000 | Pulse generator cmpl. | | 1.00 |
| 19 | 0014050163S | Hex collar screw M 5x16 SW=6 | | 2.00 |
| 22 | A44039007100 | Ignition cable | | 1.00 |
| 23 | 54739093000 | SPARK PLUG | MXC, EXC | 1.00 |
| 25 | 55639006000 | Ignition coil | | 1.00 |
| 26 | 0025060256 | HH collar screw M6x25 TX30 | | 2.00 |
| 27 | A45041031000 | Engine control unit | | 1.00 |